HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION				()	
Name of Property:					
Address: 151 MAIN ST			AKA:		
City, County: Park City, Summit	County, L	Jtah	Tax Num	nber: 151	1-MAIN-A
Current Owner Name: 151 MAII				Parcel(s):	: PC-215, PC-217
Current Owner Address: PO BC Legal Description (include acrea				/ISION, (016 AC
2 STATUS/USE					
Property Category ☑ building(s), main ☐ building(s), attached ☐ building(s), detached ☐ building(s), public ☐ building(s), accessory ☑ structure(s)	Evaluatio ☑ Landm ☐ Signific ☐ Not His *National ☐ listed	nark Site cant Site storic I Register of H	Reconstruction Date: Permit #: □ Full □ Parti istoric Places: □		<u>Use</u> Original Use: Commercial Current Use: Commercial e ☑ eligible
3 DOCUMENTATION					
Alta Mira Press, a division o Roberts, Allen. "Final Report." Park	ey E Chool of Arc s of Main St of Rowman City Recor	□ abstract of ti □ tax card □ original build □ sewer permi □ Sanborn Ma □ obituary inde □ city directoric □ census reco □ biographical □ newspapers es, interviews, oric Architecture chitecture and U treet; A Guide to & Littlefield Pub nnaissance Leve	tile ling permit t ps ex es/gazetteers rds encyclopedias etc.) Attach copic c Building Inventor , 1847-1940: a Gui tah State Historica Commercial Archi lishers, Inc., 2000.	ies of all ry. Salt La ide. Salt il Society, itecture. U	ake City: 2007. Lake City, Utah: , 1991. Jpdated edition. Walnut Creek, CA:
4 ARCHITECTURAL DESCRI	PTION & I	NTEGRITY			
Building Type and/or Style: Dou	ıble-loaded	d corridor type			No. Stories: 3 ½
Additions: □ none ☑ minor □] major (de	escribe below) Al	terations: □ none	e ☑ mi	nor 🛘 major (describe below)
Number of associated outbuilding	ngs and/or	structures: \square	accessory buildi	ing(s), #	;
General Condition of Exterior M	aterials:				
☑ Good (Well maintained with	no serious pr	roblems apparent.)		
☐ Fair (Some problems are app	arent. Descr	ribe the problems.):		
Researcher/Organization: Pres	ervation S	Solutions/Park	City Municipal Co	orporatio	on Date: <u>12-2008</u>

☐ Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.):
☐ Uninhabitable/Ruin
Materials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. Describe the materials.): Site: Stone retaining walls on either side of the front façade.
Foundation: Concrete.
Walls: Front - tapestry brick, rear - common brick.
Roof: Flat roof.
Windows/Doors: Double-hung sash type, grouped ribbons of three narrow casement windows, tri-partied windows with large center rectangular windows flanked by narrow side lights. Multi-pane glazed doors are centered on the primary façade.
Essential Historical Form: ☑ Retains ☐ Does Not Retain, due to:
Location: ☑ Original Location ☐ Moved (date) Original Location:
Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including datesknown or estimatedwhen alterations were made): The 3 ½-story brick structure has not been significantly altered over time. The two one-car garages on the ground level have been enclosed. The changes are minor and do not affect the site's original design integrity.
Setting (The physical environmentnatural or manmadeof a historic site. Describe the setting and how it has changed over time.): The setting has not been altered significantly over time. An addition was constructed on the north façade, but it is minor and does not detract from the original setting.
Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): The physical evidence from the period that defines this as a typical early twentieth century apartment block are the simple massing, center entrance, symmetrically window and door openings, brick exterior, and flat roof.
Feeling (Describe the property's historic character.): The physical elements of the site, in combination, convey a sense of life in a western mining town of the early twentieth century.
Association (Describe the link between the important historic era or person and the property.): The double-loaded corridor type apartment building was a common building type constructed in Utah during the early 20th century. It reflects the residential development patter in Park City during the mature mining period.
5 SIGNIFICANCE
Architect: ☑ Not Known ☐ Known: (source:) Date of Construction: c. 1926 ¹
Builder: ☑ Not Known ☐ Known: (source:)
The site must represent an important part of the history or architecture of the community. A site need only be significant under one of the three areas listed below:
1. Historic Era: ☐ Settlement & Mining Boom Era (1868-1893) ☑ Mature Mining Era (1894-1930) ☐ Mining Decline & Emergence of Recreation Industry (1931-1962)

¹ Summit County Recorder.

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's houses are the largest and best-preserved group of residential buildings in a metal mining town in Utah. As such, they provide the most complete documentation of the residential character of mining towns of that period, including their settlement patterns, building materials, construction techniques, and socio-economic make-up. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining community.²

- 2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):
- 3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.


Photo No. 1: East elevation. Camera facing west 2006.

Photo No. 2: Southeast oblique. Camera facing northwest, 2006.

Photo No. 3: Southeast oblique. Camera facing northwest, 1995.

² From "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.

					1	(F	A Company
Location	f Bldg. APT BLD	-	Sr. No.	151 M	AIN S		NET LL. 2.C. Th
Kind o	f Bldg. APT BEB	T 1	2 2 4	Cost \$	119.	70	x%
Class_				Sq. Ft.	Fact	or	Totals
Stories	Dimensions	Cu.		1425		1	11970
3	х х	42	750	1420	.20	-	77.70
	x x						BARRIOT IN
	x x		Walls	- F	Roof		
Att. G		C Duildin		1	Additions	7	on a bloom
V - 100	Description			None	MATE A		moccupied.
Founda	valls TAP, BRK, front	onc.	on Bo	Jek.		9	Ind floor
Ext. W	ion— FloorsWal	La Como	Clas	THE YEAR			no temants
Insulati	rype Flox	" Med	BI	0,			st floor
			Large	STATE OF THE STATE		- 11	owner 5
	rs— Small Med						nes dence
The state of the s	Small Med			@ 100	175		40% 0851
	s — Front		V	a			
				@ @			163 ADD
	ent Entr.				The sale	69	163 *
Planter	Bsmt. $-\frac{1}{4}\frac{1}{3}\sqrt{\frac{1}{2}}\frac{2}{3}\frac{3}{4}$	99/cmp = 64.	Floor	@	171		2445
Cellar-	Apt Rooms F	in	Unfi	n.		1	4 BASINS
Bsmt.	Rooms Fin.	11	ofin.				
Attic	Rooms Fin.	Tub	1	Travs	350		1700
	Basin Basin S	Sink /	3	oile 63	190		6 ShOWERS
Plumb	urls.	Ftns.	St	Shr. Shr	200		-00
	Dishwasher	G	arbage	Disp.			3837%
Heat-	- Stove H.AS	ream 🔟	StkrV	B r	In Speen	reation	* 11
Oil	Gas Coal	Pipele	ss	Radiant			100
	Cond						78030 1030
	Fir Hd.						ARCOIT
	- Fir Hd. W				40		111111111111111111111111111111111111111
	ets Mantels_				-		1990
	- WallsWainso			ors	LI CALL		
	ical— Outlets			\			Noolsoliscente
Storm	Sash— WoodMe	tal	Doors_	Sash\	1		Car 1964
Metal	Awnings	S 114			100	, 7	ld.
	ne car basemen				THE REAL PROPERTY.		
V V V	too narrow be	n woo	Clri	arec	Vine i		
1 February 1				TOTAL LEG	157	6	1516
_	Additions		, ,	veries Value			13486
Year	Built 1926 Avg.	31	Depr	Col. 1 2 3	456 6	1 %	
	Owner - Tenan			Val. Minus I		_	8226
Inf.	by Neighbor - Reco	ord - Est.		or Rem.		%	. 3500
Remo	odel Year Est. Cost		P	Bldg. Value	/_		\$ 3290
Gara	ge— ClassDe	pr. 2% 39	6				
Cars	Floor	_Walls _		Roof	_ Doors		THE NUMBER
Size	xAge_		_ Cost _		x	_%	
Othe	1		100				
13,5	N)	-	,	3	ling Value		\$
App	raised 12-10	3-	19-57	Ву	1551		



TC . 74 REV. 54 50M. 15M


STATE OF UTAH - STATE TAX COMMISSION ...



- - 3

OF...... Card Number

	. Q	in	Ca	M					
Owners	.//,	3 Bk							
					- 151	No	main 5	F	6.4
	Blug.		Tuno	1624	Cost & Z	0	520×104	2	×1023 HL
Stories	Dimensio				Factor			Т	Totals
TAMES TO A STATE OF THE STATE OF							Totals	-	Totals
_3	25 x 5 7		42	150	48	\$	21958	\$	
	х	х						H	
	x		,	Arr 11	- CI			-	
Att. Gar	Desc	ription o			C1	=	Additions		Additions
_				_		-	Additions	F	Additions
	ion—Stone _					-	/ Re		m 0 14 00)
	Ils Tap Brat				nBih	-	/	- Gr	100-79
	pe Jle			-		1		H	1801
	-Small				\	-			
	mall				1 /	0	263		
	Front				1/		~65	H	
					-@/	_			7
Transfer of the second					a				
The state of the s				-/	(@ 				
Ext. Bas	se. Entrysmt. — 1/4 1/3	7/2	#9	e.25	(a) t		1246	Н	
Cellar-B	smt. — ¼ ⅓ ar	(12) 73° 9	4 Full.	F	loor	unc	1276		
				/	1			Н	
	it-Apt.		/						
Attic Ro	oms Fin / Class _			Unfin					
	Rasin /	14	ink	/_ To	ilet 6		4020		
Plumbin	Wtr. Sfi	tr	Shr.	St. 6	0.T. 15	1	4000		
	the state of the s		/	Garbage		1			
Heat—St	ove H.A.	FA/_	_HW	Stkr	Elec	1	,		
Oil _	_Gas (Coal	Pipele	ess F	Radiant	1	ene		
Air Cond	i. — Full _			Zone _		1			
Finish-	Fir I	Hd. Wd.		Par	iel				
Floor-F	ir	Hd. Wd		Oth	er	_			
Cabinets		_ Mante	els			_			
Tile -W	alls	_Wains	cot	F	loors				
Storm S	ash-Wood I	o s.	;	Metal D.	S				
Awnings	s — Metal _		F	iberglass					
			_						
						-			
		_				-			-
Total Ad	ditions						5529		
Year Bu	ilt. <u>1926</u>	Avg. 1	1931	Replacer	ment Cost		27487		
196		Age 2		Obsoles	ence		9		
Inf. by	Owner - Te Neighbor -	nant- 2	igr	Adj. Bld	l. Value				
IIII. by	(Neighbor -	Record -	Est.	Conv. Fa	actor		x.47		
		Replace	ment (Cost—194	0 Base				
	A	Deprecia	ation C	Column 1	234 5	6			
		1940 Ba	se Cost	, Less De	preciation				
Total Va	lue from reve	erse side							/
			To	otal Buil	ding Valu	e	\$	1	
Appraise	ed ① //- /=	5		1968	8 By 13	3:	3	-	10.5
	ed ②				_ By		Ulile .	14	100



RESIDENTIAL OUT BUILDINGS	Age	Size	Area	Fac- tor	Cost	Conv. Fac.		Depr. Value
		x				.47		
		x				.47		
ALTERNATION NAMED IN COLUMN		x				.47		
		x				.47		
		x				.47		
		x				.47		
Garage — Class Depr. 2% Cars Floor Wall				De	oors			
Size x Age								
1940 Base Cost	x	_% Depr.						
Average Year of	Cons	truction	Comp	utatio	on:			
Average Year of	86	% X 3	18	Year :	=	32	68	-
Year 1943 \$ 3830 =	14	of X	, ,	Year :	_		.14	
Average Year of Cons						32	82	
Average Tear of Cons	tructi	OIL -1	· Constitution of		•••	3		
CC-74 REV. 61 STATE OF UTAH - STATE TAX COMM	ISSION	, 6	t332	,				

KIND OF BUILDING	1958	1959	0961	1961	2761	61	1961	61	61	61
ast alda.	1808	7417	7822	7687	7572		7282			
40% 6	- 3236	3183	3128	3075	3021					
1464-40D							270			
GARAGE										
RESIDENCE										
TOTAL	1855	4774	4694	4612	4531		4052			Fig.
ASSESSED VALUE	0461	0/6/		18451	1812		3300			
							1			
KIND OF BUILDING	61	61	61	61	61	- 61	61	61	61	61
	4									
GARAGE										
RESIDENCE										
TOTAL										
ASSESSED VALUE									4	





