HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION					
Name of Property:					
Address: 180 DALY AVE		AKA:			
City, County: Park City, Summi	it County, Utah	Tax Numi	ber: PC-668		
Current Owner Name: PRICE (GLEN A & BARBARA J	J Parent Parcel(s):			
Current Owner Address: PO Bo	OX 214; PARK CITY, UT	Γ 84060-0214			
Legal Description (include acre PARK CITY ALSO E'LY 1/2 VA			4 MILLSITE RESERVATION TO 12 AC		
2 STATUS/USE					
Property Category ☑ building(s), main ☐ building(s), attached ☐ building(s), detached ☐ building(s), public ☐ building(s), accessory ☐ structure(s)	Evaluation* □ Landmark Site ☑ Significant Site □ Not Historic *National Register of H □ listed (date:)	Reconstruction Date: Permit #: □ Full □ Partial distoric Places: ☑ inelig	Use Original Use: Residential Current Use: Residential ible □ eligible		
3 DOCUMENTATION					
Blaes, Dina & Beatrice Lufkin. "Fin Carter, Thomas and Goss, Peter. University of Utah Graduate S McAlester, Virginia and Lee. <i>A Fie</i> Roberts, Allen. "Final Report." Par	□ abstract of t □ tax card □ original build □ sewer perm □ Sanborn Ma □ obituary ind □ city director vey □ census reco □ biographica □ newspapers voks, articles, interviews, val Report." Park City Histor Utah's Historic Architecture value of Architecture and Lead Guide to American House k City Reconnaissance Lev "Residences of Mining Bo	ding permit ding permit dit ding permit dit dips dex dex dex dex dex des/gazetteers des/gazettee	alt Lake Čity, Utah: sty, 1991. Knopf, 1998.		
4 ARCHITECTURAL DESCRI	PTION & INTEGRITY				
		"T" Catta	No Otodo 4		
Building Type and/or Style: Val	J	· ·	No. Stories: 1		
Additions: ☑ none ☐ minor [•				
Number of associated outbuild	ings and/or structures: L	accessory bulluing(s),	#;		

Researcher/Organization: Preservation Solutions/Park City Municipal Corporation Date: 12-2008

General Condition of Exterior Materials:
☑ Good (Well maintained with no serious problems apparent.)
☐ Fair (Some problems are apparent. Describe the problems.):
☐ Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.):
□ Uninhabitable/Ruin
Materials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. Describe the materials.): Site: Wood picket fence
Foundation: Not visible and therefore its material cannot be verified
Walls: Vinyl/aluminum siding
Roof: Metal
Windows: Paired and single multi-pane casement windows with false muntins.
Essential Historical Form: ☑ Retains □ Does Not Retain, due to:
Location: ☑ Original Location ☐ Moved (date) Original Location:
Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including datesknown or estimatedwhen alterations were made): Overall design of structure has not been altered over time, other than in materials (such as roofing and front door style).
Setting (The physical environmentnatural or manmadeof a historic site. Describe the setting and how it has changed over time.): Narrow lot with property line immediately adjacent to city roadway, separated by picket fence, with structure recessed from this edge no more than 10 feet. Fairly flat lot terrain, with steep hilly slope rising directly behind property line. Naturally occurring grasses and trees throughout the landscape, heavier tree foliage on the right portion of the front elevation.
Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): The physical evidence from the period that defines the typical Park City mining era homesimple methods of construction, the use of non-beveled (drop-novelty) wood siding, plan type, simple roof form, informal landscaping, restrained ornamentation, and plain finisheshave been altered and, therefore, lost.
Feeling (Describe the property's historic character.): The physical elements of the site, in combination, do not effectively convey a sense of life in a western mining town of the late nineteenth and early twentieth centuries.
Association (Describe the link between the important historic era or person and the property.): The "T" or "L" cottage (also known as a "cross-wing") is one of the earliest and one of the three most common house types built in Park City during the mining era; however, the extent of the alterations to the main building diminishes its association with the past.
5 SIGNIFICANCE
Architects of Net Known - O Known (course)
Architect: ☑ Not Known ☐ Known: (source:) Date of Construction: c. 1925¹
Builder: ☑ Not Known □ Known: (source:)
The site must represent an important part of the history or architecture of the community. A site need only be significant under one of the three areas listed below:

¹ Summit County Recorder.

						_		
1.	н	ıct	^	rı	^	H١	ra	۰
Ι.		ıoı	u			ட	а	

Settlement & Mining Boom Era (1868-1893)	
 Mature Mining Era (1894-1930)	

☐ Mining Decline & Emergence of Recreation Industry (1931-1962)

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's houses are the largest and best-preserved group of residential buildings in a metal mining town in Utah. As such, they provide the most complete documentation of the residential character of mining towns of that period, including their settlement patterns, building materials, construction techniques, and socio-economic make-up. The residences also represent the state's largest collection of nineteenth and early twentieth century frame houses. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining community.²

- 2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):
- 3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.

Photo No. 1: East elevation (primary façade). Camera facing west, 2006.

Photo No. 2: Southeast oblique. Camera facing northwest, 1995.

Photo No. 3: East elevation (primary façade). Camera facing west, tax photo.

² From "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.

SERIAL NO. RE-APPRAISAL CARD (1999 APPR. BASE)

ner's Add	iress		1		
cation	Ro	1 0	street No		
nd of Bui	2	Type 1-2-8	M		_ x
hedule	Class Dimensions	Cu. Ft.	Sg. Ft.	Actual	Totals
Stories			bos	\$	\$134
	x x		0.0	\$	\$
	x x			8	8
	X X			1	
o. of Room	110	ndition	T	Dadust	
	Description of Buildin	g	Add	Deduct	
oundation	Stone Conc.	None_	-	104	
xt. Walls_	didin	9	1		
	ated FloorsWall	clgs		-	
oof—Type	419	at. Pat		1	
	SmallMed	Lg.		1	
	allMed		- 4		
orches—I		@	1		
	Rear.		1		
ellar Ba	sm't—1/4 1/3 1/2 2/3 8/4	full-floor	30		
	Apts.—Rooms Fin.		1		
ttic Room		nfin	1		1
	Class Tub.	Trays	215	1	1
Plumbing-	TI-16 Ftns		-	10	1
Ieat—Sto	ve H. A. Steam	_SBlr	-		1
0	ilGas	Coal	-		1
	ir ConditionedIr	icinerators		1	
R	adiant—Pipeless	Hd. Wa.		A.	
Finish—	Hd. Wd. Floors-	Fir_Conc	-	1	
	Fir Mante		40	1	
Cabinets_	19		/		
Tile— ≺	WallsWain	15000			
	FloorsDrops	Fix	#		_
Lighting-	# Colotes L	red	1	85	1
10,	+ (occ and so		9	1	
	1			1	27
247		iona A	285	189	131
	Additions and Deduct	10118.	0		1.6
Net Addi	itions or Deductions				. 152
0190		REPRODUCTIO		. /	
Age_Y	rs. by Tenant I	Depr. 1-2-3-4-5-		70/100	1
)A	Records	Reproduction V	The second second	/	•
Remodel			modeling Inc.	%	5
Garage-	S 8CDepr. 20	70 0 70	solescence		\$
Cars	Walls	Ou	t Bldgs		\$
Roof	Sizex_	Age			\$
Floor	Cost	Deprecia	ted Value Ga	rage	\$
Remarks		Tot	al Building V	alue	\$
Avomar A		1			
		1			
		-		1	

R 068

73

RECORD OF ASSESSMENT OF IMPROVEMENTS

Summit		COUNTY	SERIAL	NO	10
OWNER'S NAMESWAL	nson,	Jennie	Marie		
Appress	Park	City	180 Dal	y Ave.	

Pt_ lot 26, Pt. lot 27, Blk 74 Millsite


OUT BUILDINGS	Age	Size	Area	Fac- tor	Cost	Depr. Value
		x				
*		x				
		x				
		x				
	П	x				
		x				
		x				
		x				
		x				
		x				
		. x	-			
		x				
		x	_			
		x				
		x				
22		x				
		x				

Serial No. PC 668

Location	Block 74	Millet	724 1	×- 7	
			1800	110 26	727
Class _	2	St. No.	0	arya	ve
Stories	A CONTROL OF THE CONT	Type 1 2 3 42	Cost \$	393	X 100 9
Stories	Dimensions	Cu. Ft.	Sq. Ft.	Factor	Totals
_/	x x		632		\$ 1398
	x x				
	x x				
Gar.—Ca	arport xFl	rWalls _	Cl		
	Description of			Additions	
Foundati	ion—Stone (Conc 1	None V		
Ext. Wal	lls Sidi	ng			
Insulatio	n-FloorsWal	ls Clgs	_/		
Roof Typ	oe Gab,	_Mtl. Pat	-/		
Dormers-	-Small Med.	Large	-		
Bays - S	mall Med		-		
	-Front	@			RECENTLY
Rear	-	@			RECENTLY VACATED
Porch _					LATED
Metal Aw	vnings	_Mtl. Rail			
	Entr.				
		@			
	mt. — ¼ ½ ½ ¾ ¾ F	@			
	tRooms Fin.				
Attie Roo		Unfin	-		
	Class Tub Basin Sin	Trays			
Plumbing	Wtr. Sftr.	Shr St Collet			
	Dishwasher	Garbage Disp.		3/5	
Built-in-A	ppliances				
Heat-Sto	ve KH.A Stea	m Stkr	Riv	S	
Oil	Gas Coal	Pineless Po	lient		
Air Cond.		- Mac	liant		
Finish— F	irHd. Wd.	1			
	r Hd. Wd				
Cahinete	/Mantels	Other	_		
	lsWainscot	the state of the s	1		
H O	Mar 6x8	; Metal D	S		
11100	ar uro	48 610		34	
otal Addit				349	349
ear Built		Current Va	lue		\$ 1742
12 Uge	949-43 Age 5	Commission	Adj.	%	
nf. by	Owner - Tenant - Neighbor - Record - Est	Bldg.			
	ear EstCost	Depr. Col. 1	2 3 4 5 6	35 %	
	lass Depr. 20	current Val	ue Minus Der	pr.	610
ars /	Floor That we	% 3% Carport -	Factor	,	
70- /2	_ Floor _Dirt Wall	Roof _	Doors.	-	
the-	_ x <u>20</u> Age <u>2</u>	Cost _/_	x x	30 %	40
ther					
	(1000)	Total	Building Val	ue \$	
ppraised	5-13-	10/8	1200	2.4"	The section

.....OF Card Number

Ownan	Name arve	e tries			
Location	Pt of lets 26	127 Beb	74 M	5	1
Kind of	Bldg. Res	St	180	Dalu au	
Class					
Stories	Dimensions	Type 1 2 3 &			X
		Sq. Ft.	Factor	Totals	Totals
	x x	728		8 2362	\$
	x x				
Att. Com	X X				
Att. Gar.		rlr Walls_	Cl		
	Description of	A STATE OF THE STA		Additions	Additions
	on—Stone		_Sills		
Ext. Wal	ls Siding	7 /			
		The state of the s		_	
	-Small Med				
Bays-Sn	nall Med _	Large _			
Porches-	-Front		@		
Rear			_@		
			_		
Ext. Base	mt. — ¼ ½ ½ ¾ ¾	+	@	-	
Cellar-Bsi	mt. — ¼ ½ ½ ¾ ¾	Full F	loor	40	
Bsmt. Gar	·				
Basement-	-Apt Rms	Fin. Rm	s		
Attic Room	ms Fin	Unfin		160	-
	Class	TubT	rays		X X
Plumbing	Basin Si	ink Toi	let	_	
	Wtr. Sftr.	Shr. St	о.т	550	
West Stee	Dishwasher veH.A FA	Garbage I	Disp	230	
neat—Sto	ve H.A FA_	_ HW Stkr_	Elec	-	
	Gas Coal				
	- Full				
	r. Hd. Wd.			+	
	Hd. Wd		•——		
Cabinets .	Mantel			-	
	sWainsco			1 -	
	h-Wood D. / S			23	
Awnings -	— Metal	Fiberglass _		-	
	11		-		-
Total Addit		0		775	
Year Built		90 Replaceme	ent Cost	3/37	
FDN	Age 2.	Obsolesce	nce		5
nf. by	Owner - Tenant	Adj. Bld.	Value		
by)1	Neighbor - Record - E	est. Conv. Fac	tor	x.47	
	Replaceme	ent Cost—1940		9.5	
		ion Column 1 2			
		Cost, Less Depr			1 -1 - 3-
otal Value	from reverse side	FARAGE	The same of the sa	71.	
13 =1		Total Buildin	ng Value	8	
	0_11-5-	1968			
naroised /					



x x x x x x Cost 2 % Depri	of RK		Doors x 47 %	.47 .47 .47 .47 .47	
x x x x x	0f R K		Doors x 47 %	.47	
x x x Ro	of RK		Doors _ x 47 %	.47	
x x Ro	of RK		Doors x 47 %	.47	3
x Ro	of RA	1	Doors x 47 %	.47	
Tost 2	01RK	1	Doors		-
Cost 2	of RK	1	Doors x 47 %		-
_ % Depi	·	ntal		-	71
-	ı				

STATE OF UTAH - STATE TAX COMMISSION

RWD95-VWD248 XWD409 OUT

S 48 ft lot26 & N 4 ft lot 27 Blk74 MR Park City Also E'ly & vacated Anchor Ave. adjacent to said lots.

(Serial No.-Owner-Add.-Desc. of Property)

					Nud -			Towns of the same
								L NO.
							22 × 104 1114	FRONTAGE OR AREA
							1,144	DEPTH
							30	RATE
ASSESSED VALUE						A.		CORNER INFLU- ENCE
ALUE	TOTAL							RATE
255	h861						h861	VALUE
	1	1	S 57 (- new pr			





