HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION			
Name of Property:			
Address: 305 Park Ave		AKA:	
City, County: Park City, Summi	t County, Utah	Tax Numb	per: PC-37
Current Owner Name: MARTZ Current Owner Address:PO BC Legal Description (include acre	X 1963 PARK CITY, U	IT 84060-1963	
2 STATUS/USE			
Property Category ☑ building(s), main ☐ building(s), attached ☐ building(s), detached ☐ building(s), public ☐ building(s), accessory ☐ structure(s)	Evaluation* □ Landmark Site ☑ Significant Site □ Not Historic *National Register of □ listed (date:)	Reconstruction Date: unknown Permit #: □ Full ☑ Partial Historic Places: ☑ ineligi	<u>Use</u> Original Use: Residential Current Use: Residential
3 DOCUMENTATION			
Blaes, Dina & Beatrice Lufkin. "Fin. Carter, Thomas and Goss, Peter. University of Utah Graduate S McAlester, Virginia and Lee. <i>A Fie</i> Roberts, Allen. "Final Report." Park	□ abstract of □ tax card □ original bui □ sewer pern □ Sanborn M □ obituary ind □ city directo vey □ census red □ biographica □ newspaper boks, articles, interviews al Report." Park City Histo Utah's Historic Architecture chool of Architecture and ald Guide to American Hou oc City Reconnaissance Le "Residences of Mining Bo	ilding permit mit flaps dex pries/gazetteers cords al encyclopedias rs coric Building Inventory. Salt re, 1847-1940: a Guide. Sa Utah State Historical Socie uses. New York: Alfred A. Revel Survey. Salt Lake City:	alt Lake City, Utah: tty, 1991. Knopf, 1998.
4 ARCHITECTURAL DESCRI	PTION & INTEGRITY		
Building Type and/or Style: Cel Additions: ☐ none ☐ minor ☐ Number of associated outbuildi General Condition of Exterior M	☑ major (describe below) // ngs and/or structures: [Alterations: □ none □ r	•

Researcher/Organization: Preservation Solutions/Park City Municipal Corporation ____ Date: ___ Dec. 2008

☑ Good (Well maintained with no serious problems apparent.)
☐ Fair (Some problems are apparent. Describe the problems.):
☐ Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.):
☐ Uninhabitable/Ruin
Materials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. Describe the materials.): Foundation: The foundation is not visible in the available photographs and therefore its material or existence cannot be verified. Tax records note that it was stone in 1949 and 1957.
Walls: The exterior walls are clad in wooden drop/novelty siding.
Roof: The hipped roof is sheathed in composition shingles. A siding-clad chimney shaft is visible on the façade.
Windows/Doors: Windows include one-over-one double-hung sash in simple casing with slightly projecting sills. The second floor façade windows are placed in pairs in horizontal openings. The front-facing gable end has a round window in the attic level.
Essential Historical Form: ☑ Retains ☐ Does Not Retain, due to:
Location: ☑ Original Location ☐ Moved (date) Original Location:
Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including datesknown or estimatedwhen alterations were made): The original house appears on Sanborn insurance company maps in 1907 and tax records in both 1949 and 1957 as a two story house with a rectangular footprint, narrow end to the street. Both tax records noted that the house was vacant at the time of inspection. The tax record for 1968, the 1978 site form, and an undated slide in the file show a single-story frame house. Perhaps there was a fire in the 1957-1968 period. The house was capped with a full second floor and attic between 1978 and 1995, creating a Central-block-with-projecting-bay type house. No photographs are available of the original two-story house. The accuracy of the reconstruction is not evident.
Setting (The physical environmentnatural or manmadeof a historic site. Describe the setting and how it has changed over time.): Like most of the historic neighborhoods in Park City, the overall setting is a compact streetscape with narrow side yards and other homes within close proximity.
Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): Much of the physical evidence from the period that defines the typical Park City mining era home has been altered and, therefore, lost.
Feeling (Describe the property's historic character.): The physical elements of the site, in combination, do not effectively convey a sense of life in a western mining town of the late nineteenth and early twentieth centuries.
Association (Describe the link between the important historic era or person and the property.): The original frame house was a house type built in Park City during the mining era; however, the extent of the alterations to the main building diminishes its association with the past.
The extent and cumulative effect of alterations to the site render it ineligible for listing in the National Register of Historic Places.
5 SIGNIFICANCE
Architect: ☑ Not Known ☐ Known: (source:) Date of Construction: c. 1895 ¹

¹ Summit County Recorder.

Builder: ☑ Not Known	☐ Known:	(source:)	
The site must represent significant under one of t		part of the history or architecture of the community. as listed below:	A site need only be
Historic Era: Settlement & Minin Mature Mining Era Mining Decline & E	(1894-1930)	` '	

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's houses are the largest and best-preserved group of residential buildings in a metal mining town in Utah. As such, they provide the most complete documentation of the residential character of mining towns of that period, including their settlement patterns, building materials, construction techniques, and socio-economic make-up. The residences also represent the state's largest collection of nineteenth and early twentieth century frame houses. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining community.²

- 2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):
- 3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.

Photo No. 1: East elevation (primary façade). Camera facing west, 2006.

Photo No. 2: Southeast oblique. Camera facing northwest, 1995.


The term of the te

Photo No. 3: Photo of c. 1970 slide showing a one story frame house.

² From "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.

SERIAL NO. RE-APPRAISAL CARD (1940 APPR. BASE)


Location					Tall Tall
Kind of Bui	Iding Res		Street No.	205 B	ark Ou
Schedule	Class 5	Туре 1-2-3			-
Stories	Dimensions	Cu. Ft.	Sq. Ft.	Actual	X
2			. 04	Factor	Totals
	x x		1083	\$ -	\$ 53)
	828			\$	\$
	X X			\$	\$
No. of Room	ns 4 9-4- Up Cor				
	Description of Building	3	Add	Deduct	
Foundation-	0 . / 1	None			
Ext. Walls_	Siding.				
	ted-FloorsWalls_	Clgs			
Roof-Type_	696. Mat	She		1	lacali
Dormers-Si	mallMed	Lg			acall
Bays-Small	Med	Lg		t	rut 1
Porches-Fr	ont	@ 1.75	150		0
R	ear Enclosed - 60 "	@ 1.80	108		Nº - 100
Cellar Basn	n't—¼ ¼ ½ % ¾ ful	1-floor Dirt			5
	ots.—Rooms Fin.				Jose
Attic Rooms	Fin. Unfi			. /	,
	Class / Tub 2 Basin 2 Sink /	TraysToilet_2	1		ond It
- ramoing	UrlsFtns DishwasherGarbage	Shr	160		
Heat-Stove_	H. A. Steam S. Gas Coa	Blr	, 00		
	ConditionedIncin	erators			
1	ant—Pipeless				
$\mathbf{Finish} = \begin{cases} \mathbf{n} \\ \mathbf{Fi} \end{cases}$	/ Floors— {	Hd. Wd	-		
Cabinets	/	Conc.			
(Wal			-		
Tile— {	- Wanseon		1		
(Floo		1		-	
ngnting—La	mpDropsFi	х			
	100 mars 100 mars 100 mars		1618		ranh
	litions and Deductions_		418		5331
Net Additions	or Deductions			<u>s</u> +	418
FIE	Est. REPR	ODUCTION V	ALUE	8 0	5755
ge Yrs. by	Tenant Depr.	192-8-4-5-6	67/33	% s	
	Neighbors Records Reprod	luction Val. Mi	us Depr	8	1898
emodeled	Est. Cost	Remodeli		% \$	1
arage—S 8_	CDepr. 2% 8%			8	A
ars	_Walls	Out Bldg	2.5020.00	8	
oof	Size_x_Age_				
loor	Cost	Depreciated Va	lue Garage	8	
emarks		Total Buil		-	
AND THE PROPERTY OF THE PARTY O		Total Bull	ung value_	\$	



OUT BUILDINGS	Age	Size	Area	Fac- tor	Cost	Depr. Value
		x				
		x				
		x				
		x				
		x				
		x				
		x			14	
		x				
		x				
		x		-		
		x				
		x				
		x				
		x				
	4	x				
		x				
		x				

Kind of	Bldg. RES		St. No.	305	P	ank	AVS	
Class _	. 5	Туре	123.	Cost \$				х
Stories	Dimensions	C	u. Ft.	Sq. Ft.		Factor	-	Totals
2	x x			108	3		\$ 1	4779
	x x							
	x x							
Gar.—C	Carport x	_Flr	_Walls _	C1				
	Description	on of Buildi	ngs		Add	itions		
	tion—Stone		-	None			Va	cated
	alls Sid	1		\times	-		Rec	isonabl
	on—Floors				-		go	0.2
Roof Ty	pe gall	Mtl	Dha		-		Co	nd 1+10
	s-Small				-		11	70 08
	SmallMe				<u> </u>	_	-	
	-Front					50	-	
Medical -			The state of the s			08		
Porch _			@	9	-		-	
	wnings		100000000		-		-	
Basemer	nt Entr.		@	9 ———			-	
	3		@	Λ .	-	0	1	
	3smt. — ¼ ¼ ½ ¾					90		
	ptRooms							
Attic Ro	ooms Fin.				-			
	Class Basin	_ Tub	Tra:	ys				
Plumbin	Wtr. Sftr.	Shr. Si	1011	O.T.				
	Dishwasher	Ga	rbage Dis	р		60		
Built-in-	-Appliances							
Heat—S	Stove H.A	_Steam	Stkr	_Blr				
Oil	Gas Coal	Pipele	ess R	adiant				
Air Con	d							
Finish-	FirHd	l. Wd						
Floor-	Fir Hd. \	Wd	Other					
Cabinets	sMante	els			- 1	40		
Tile - W	VallsWai	inseot	Floor	s		-	251	
Storm S	ash— Wood D	. s; s	Tetal D.	s				
Total Ac	dditions				100	18		
Year Bu	iltAv	g. ,	Current	Value			\$ 5	5821
	Age		Commissi	on Adj.	- 1	0 %	****	-583
Inf. by	Owner - Tenant Neighbor - Recor			g. Value				524
Remodel	The state of the s			Value Minu				
	- Class D			t — Factor			\$	21:
	Floor							
	x Ag					pt.		
Other			_ Cost		x	%		
Julet			T	tal Buildin	a Vale	4		
	. 1	5	10	car Buildin	e Agin		\$	

Kind -	Dlda	12.0		2	25 0		
Class	Bldg.		St. 3			K	SUE
Class	7		Type 1 2 3/4	Cost \$ _			_ X
Stories	Dime	nsions	Sq. Ft.	Factor	Totals	_	Total
-	х	х	1080		8 4495	\$	
	x	х		- 4			
	х	x					
Att. Gar.			Flr Walls_	Cl	_		
			n of Buildings		Additions		Addition
Foundation	n—Stone	-	_ Conc.	_ Sills			
Ext. Wall)			
Roof Type	_ 6	al	MtlAL4	in c	A -		
Dormers-	-Small	Ме	ed Large	e			
Bays—Sm	all	Med _	Large				
			163		155		
Rear							
Porch							
			1 1				
			1-1-				
			34 Full Fl			\top	
Bant. Gar.						\top	
			Fin. Rm:	s.		11	
			Unfin			$\top \top$	(
	/ Class		Tub / T	ma via			
Dlumb!	Basin .	—/_s	Sink /_ Toil	et _/	550	11	
Plumbing	Wtr. S	ftr	Sink Toil	о.т			
	Dishwa	isher	Garbage D	isp.			
Heat—Stove	H.A	· FA _	HWStkr_	Elec			
Oil	Gas X	Coal	Pipeless Ra	diant			
Air Cond	- Full		Zone				
Finish—Fir		Hd. Wd.	Panel				
Floor-Fir-		Hd. Wd	Other				
			ls				
Tile —Walls		Wainsc	otFloo	ors			
Storm Sash	-Wood	D S	; Metal D	/ s	30		
			Fiberglass _				
						\vdash	
otal Addition	ons				911		
ear Built.	1895	Avg. 16	15-95 Paul		5050	-	
-		Age 2.			23/0		-
(60)	vner Te		- G SECTEBEEN			_	W-9
nf. by	eighbor -	Record - I	Adj. Bld. V				
	-	2	Conv. Facto		71.0		
			ent Cost—1940 I		and the		
			ion Column 12				
otal Value f			Cost, Less Depre	ciation			Tar
otal Value f	rom reve	rse side					
			Total Building				



RESIDENTIAL OUT BUILDINGS	Age	Size	Area	Fac- tor	Cost	Conv. Fac.	Adj. Cost	Depr. Value
		x	-			.47		11
2		x				.47		
*		x				.47		
		x				.47		
		x				.47		1.1
		x				.47		
Cars Floor Wal Size x Age 1940 Base Cost		_Cost			x 47 %	6	-	
			To					
REMARKS					-0.000			
584 Tun 11 (10) (10) (10) (10) (10)						-		
	_		-				-	

STATE OF UTAH - STATE TAX COMMISSION

SE Corner

Researcher: Date:

Philip F. Notarianni

June, 1978

Utah State Historical Society Historic Preservation Research Office

Structure/Site Information Form

IDENTIFICATION SERVED	Street Address: Name of Structure:	305 Park Ave.			Plat _i	R.	Lot S.	1-2
ENTIFIC	Present Owner:	Kenneth J. and Barba	ara A. Martz		UTM	1:		-
A SECURE OF SECURE	Owner Address:	P.O. Box 437, Park (AND ADDRESS OF THE PARTY OF THE	84060	Tax	T C	37	
2	Original Owner:		Construction	Date: @1895	Demol	ition D	ate:	
	Original Use:	residential						
AGE/CONDITION/USE	Present Use: Single-Family Multi-Family Public Commercial	☐ Park☐ Industrial☐ Agricultural	□ Vacant □ Religious □ Other		Occ	upants		
AGE/0	Building Condition: Excellent Good Deteriorated	□ Site □ Ruins '	Integrity: □ Unaltered Minor Alteration □ Major Alteration					opportunit di Propor
STATI	Preliminary Evaluation Significant Contributory Not Contributory Intrusion	on:		inal Register S National Landmark National Register State Register		ource		
4 z	Photography: 11/77 Date of Slides: Views: Front □ Side □ Re	ar □ Other □		notographs: ont □ Side □ Rear □	Other 🗆			
DOCUMENTATION	Research Sources: Abstract of Title Plat Records Plat Map Tax Card & Photo Building Permit Sewer Permit PSanborn Maps City Directories Biographical Encyclopedia County & City Histories Personal Interviews Newspapers Cutah State Historical Socie		S	□ LDS Church Arch □ LDS Genealogica ✓ U of U Library □ BYU Library □ USU Library □ SLC Library □ Other				

Bibliographical References (books, articles, records, interviews, old photographs and maps, etc.):

Summit County Recorder and assessor Records, Summit County Courthouse, Coalville, Utah. Sanborn Maps, Park City, Utah, 1889,1900,1907.

unknown Architect/Builder:

Building Materials: wood


Building Type/Style: residential

Description of physical appearance & significant architectural features:

(Include additions, alterations, ancillary structures, and landscaping if applicable)

Gne-story frame dwelling with gable roof, having an aluminum covering. A front porch, with gable roof, exists on the northeast section. Ornate woodwork remains on the porch. In addition, decorative woodwork remians around a corner window in the southeast corner. Wood framing around the windows appears to have remained the same as in a 1940's tax photo.

From Sanborn Maps:



Not on 1889 Maps: Appears the same in 1900. structure a two story.

Statement of Historical Significance:

- Aboriginal Americans
- Agriculture
- ☐ Architecture ☐ The Arts
- □ Commerce

- Communication
- □ Conservation □ Education
- □ Exploration/Settlement
- □ Industry

- □ Military
- Mining Mining
- ☐ Minority Groups
- ☐ Political □ Recreation

- □ Religion
- ☐ Science
- ☐ Socio-Humanitarian
- □ Transportation

Significant as an early mining town cottage, contributory to the Park City residential district.

In 1883 the property, including a house and stable, was deeded to Alex M. Smith by J.M. Froiseth, and in 1885 to Phoebe Smith. By 1896 the property belonged to Gilbert D. Gregor.



