

HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION

Name of Property:

Address: 563 Woodside Avenue

AKA:

City, County: Park City, Summit County, Utah

Tax Number: PC-347-A-2

Current Owner Name: Rhodes Investments VII, Limited Partnership, LLLP Parent Parcel(s): PC-347-A

Current Owner Address: 2425 E Camelback Road, Ste 750, Phoenix, AZ 85016

Legal Description (include acreage): 0.04 acres; ALL OF LOT 16 BLK 28 AMENDED PLAT OF PARK CITY SURVEY.

2 STATUS/USE

Property Category

- building(s), main
- building(s), attached
- building(s), detached
- building(s), public
- building(s), accessory
- structure(s)

Evaluation*

- Landmark Site
- Significant Site
- Not Historic

Reconstruction

- Date:
- Permit #:
- Full
 - Partial

Use

- Original Use: Residential
- Current Use: Residential

- *National Register of Historic Places: ineligible eligible
- listed (date:)

3 DOCUMENTATION

Photos: Dates

- tax photo:
- prints:
- historic: c.

Drawings and Plans

- measured floor plans
- site sketch map
- Historic American Bldg. Survey
- original plans:
- other:

Research Sources (check all sources consulted, whether useful or not)

- abstract of title
- tax card
- original building permit
- sewer permit
- Sanborn Maps
- obituary index
- city directories/gazetteers
- census records
- biographical encyclopedias
- newspapers
- city/county histories
- personal interviews
- Utah Hist. Research Center
- USHS Preservation Files
- USHS Architects File
- LDS Family History Library
- Park City Hist. Soc/Museum
- university library(ies):
- other:

Bibliographical References (books, articles, interviews, etc.) Attach copies of all research notes and materials.

Blaes, Dina & Beatrice Lufkin. "Final Report." Park City Historic Building Inventory. Salt Lake City: 2007.

Carter, Thomas and Goss, Peter. *Utah's Historic Architecture, 1847-1940: a Guide*. Salt Lake City, Utah:

University of Utah Graduate School of Architecture and Utah State Historical Society, 1991.

McAlester, Virginia and Lee. *A Field Guide to American Houses*. New York: Alfred A. Knopf, 1998.

Roberts, Allen. "Final Report." Park City Reconnaissance Level Survey. Salt Lake City: 1995.

Roper, Roger & Deborah Randall. "Residences of Mining Boom Era, Park City - Thematic Nomination." National Register of Historic Places Inventory, Nomination Form. 1984.

4 ARCHITECTURAL DESCRIPTION & INTEGRITY

Building Type and/or Style: Crosswing / Vernacular

No. Stories: 1 1/2

Additions: none minor major (describe below) Alterations: none minor major (describe below)

Number of associated outbuildings and/or structures: accessory building(s), # _____; structure(s), # _____.

General Condition of Exterior Materials:

Researcher/Organization: Dina Blaes/Park City Municipal Corporation Date: November, 08

- Good (Well maintained with no serious problems apparent.)
- Fair (Some problems are apparent. Describe the problems.):
- Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.):
- Uninhabitable/Ruin

Materials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. Describe the materials.):

Site: Gradual rise from roadway to rear of lot. Front yard significantly regarded to accommodate driveway, parking area, basement entrance. Raised beds, wood entry stair.

Foundation: Concrete and stone veneer.

Walls: Upper walls are clad in drop siding, some of which appears to be original. Extended shed roof porch is supported by square columns. Lower level clad in drop siding and stone veneer.

Roof: Crosswing, intersecting gable, and dormers clad in asphalt shingles.

Windows: Single and paired double-hung units.

Essential Historical Form: Retains Does Not Retain, due to:

Location: Original Location Moved (date _____) Original Location:

Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including dates--known or estimated--when alterations were made): The crosswing frame house has been significantly altered, though some original elements appear to have been restored. The crosswing roof form has been altered with a large gable front addition that springs from the original ridge line. Gable dormers have been added to the stem wing and the original gable. The window openings have been altered from what is seen in the tax photo, but evidence of infill siding seen in both the tax photo and 1995 photo indicates the current window openings more accurately depict what was built originally. A large rear and basement addition with garage have been added. The additions were constructed prior to 1995.. The changes are significant and diminish the site's original character.

Setting (The physical environment--natural or manmade--of a historic site. Describe the setting and how it has changed over time.): Modifications to the setting have been significant. 1907 Sanborn Insurance Map and the tax cards indicate two frame accessory buildings as late as 1968, but they appear to have been replaced by the large rear additions. The re-grading and paving in the front yard have replaced the gradual slope from roadway to house that is typically seen on Park City's historic sites. Landscaping is information and includes evergreens and native perennials.

Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): Much of the physical evidence from the period that defines the typical Park City mining era home has been altered and, therefore, lost.

Feeling (Describe the property's historic character.): The physical elements of the site, in combination, do not effectively convey a sense of life in a western mining town of the late nineteenth and early twentieth centuries.

Association (Describe the link between the important historic era or person and the property.): The "T" or "L" cottage (also known as a "cross-wing") is one of the earliest and one of the three most common house types built in Park City during the mining era; however, the extent of the alterations to the main building diminishes its association with the past.

The extent and cumulative effect of alterations to the site render it ineligible for listing in the National Register of Historic Places.

5 SIGNIFICANCE

Architect: Not Known Known: (source:)

Date of Construction: c. 1905¹

Builder: Not Known Known: (source:)

The site must represent an important part of the history or architecture of the community. A site need only be significant under one of the three areas listed below:

1. Historic Era:

- Settlement & Mining Boom Era (1868-1893)
- Mature Mining Era (1894-1930)
- Mining Decline & Emergence of Recreation Industry (1931-1962)

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's houses are the largest and best-preserved group of residential buildings in a metal mining town in Utah. As such, they provide the most complete documentation of the residential character of mining towns of that period, including their settlement patterns, building materials, construction techniques, and socio-economic make-up. The residences also represent the state's largest collection of nineteenth and early twentieth century frame houses. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining community.²

2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):

3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.

Photo No. 1: Southeast oblique. Camera facing northwest, 2006.

Photo No. 2: East elevation (primary façade). Camera facing west, 2006.

Photo No. 3: East elevation (primary façade). Camera facing west, 1995.

Photo No. 4: Southeast oblique. Camera facing northwest, tax photo.

¹ 1907 Sanborn Insurance Map.

² From "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.

SERIAL NO.
RE-APPRAISAL CARD (1940 APPR. BASE)

Owner's Name _____
 Owner's Address _____
 Location _____

Kind of Building Res Street No. _____
 Schedule 1 Class 3 Type 1-2-3-4 Cost \$ _____ X _____ %

Stories	Dimensions	Cu. Ft.	Sq. Ft.	Actual Factor	Totals
1	x x		756	\$ —	\$ 1551
	x x			\$	\$
	x x			\$	\$

No. of Rooms 40 2 Attic Condition _____

Description of Building	Add	Deduct
Foundation—Stone Conc. None <input checked="" type="checkbox"/>		116
Ext. Walls <u>Siding</u>		
Insulated—Floors Walls Clgs.		
Roof—Type <u>Bob.</u> Mat. <u>Pol. Shg.</u>		
Dormers—Small Med. — Lg.		
Bays—Small Med. — Lg.		
Porches—Front <u>60" @ 1.25</u>	75	
Rear @		
Cellar—Basmt— $\frac{1}{4}$ $\frac{1}{2}$ $\frac{3}{4}$ full-floor <u>Conc.</u>	75	
Basement Apts.—Rooms Fin. —		
Attic Rooms Fin. <u>2</u> Unfin.	267	
Plumbing— Class <u>1</u> Tub <u>1</u> Trays _____ Basin <u>1</u> Sink <u>1</u> Toilet <u>1</u> Urns _____ Ftns. _____ Shr. _____ Dishwasher _____ Garbage Disp. _____	350	
Heat—Stove H. A. <input checked="" type="checkbox"/> Steam <input checked="" type="checkbox"/> S. <input checked="" type="checkbox"/> Blr. _____ Oil _____ Gas _____ Coal <input checked="" type="checkbox"/>		
Air Conditioned _____ Incinerators _____	708	
Radiant—Pipeless _____		
Finish— Hd. Wd. <input checked="" type="checkbox"/> Floors— Fir. <input checked="" type="checkbox"/> Hd. Wd. <input checked="" type="checkbox"/> Conc. _____		
Cabinets <u>1</u> Mantels _____	40	
Tile— Walls _____ Wainscot. _____ Floors _____		
Lighting—Lamp _____ Drops <input checked="" type="checkbox"/> Fix. _____ <u>Wolbedlined - 6 @ 20"</u>	120	

Total Additions and Deductions 1475 236 1551
 Net Additions or Deductions -236 \$ +1239

Ave Age 35 Yrs. by Est. Owner Tenant Neighbors Records

REPRODUCTION VALUE \$ 2790
 Depr. 0-1-2-3-4-5-6 48/52 % \$ _____
 Reproduction Val. Minus Depr. \$ 1451

Remodeled Est. Cost _____ Remodeling Inc. _____ % \$ _____
 Garage—S 8 C _____ Depr. 2% 3% _____ Obsolescence _____ \$ _____
 Cars _____ Walls _____ Out Bldgs. _____ \$ _____
 Roof _____ Size x Age _____ \$ _____
 Floor _____ Cost _____ Depreciated Value Garage _____ \$ _____

Remarks (27yr Ave Used - 1941) Total Building Value \$ _____

Appraised 10/1949 By CAO & AJ







563

561



563

561