HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION							
Name of Property: State Bank of Address: 405 MAIN ST City, County: Park City, Summit Current Owner Name: 405 MAIN Current Owner Address: 1635 N Legal Description (include acres	County, Utah N STREET LLC NORTHSHORE CT, PA	<i>Parent Par</i> RK CITY, UT 84098	, ,				
2 STATUS/USE							
Property Category ☑ building(s), main □ building(s), attached □ building(s), detached □ building(s), public □ building(s), accessory □ structure(s)		Reconstruction Date: Permit #: □ Full □ Partial Historic Places: □ ineligib 1979 - Park City Main Str					
3 DOCUMENTATION							
Photos: Dates ☑ tax photo: ☑ prints: ☐ historic: c. Drawings and Plans ☐ measured floor plans ☐ site sketch map ☐ Historic American Bldg. Surve ☐ original plans: ☐ other:	□ abstract of t □ tax card □ original buil □ sewer perm □ Sanborn Ma □ obituary ind □ city director ey □ census reco	ding permit nit aps lex ries/gazetteers ords I encyclopedias	Street Historic District) es consulted, whether useful or not) city/county histories personal interviews Utah Hist. Research Center USHS Preservation Files USHS Architects File LDS Family History Library Park City Hist. Soc/Museum university library(ies): other:				
Bibliographical References (boo	oks, articles, interviews,	etc.) Attach copies of a	ll research notes and materials.				
Alta Mira Press, a division o	Utah's Historic Architecture chool of Architecture and Us of Main Street; A Guide to from Rowman & Littlefield Puln Street Historic District."	e, 1847-1940: a Guide. Sal Jtah State Historical Society o Commercial Architecture. blishers, Inc., 2000. National Register of Historic	It Lake City, Utah: y, 1991. Updated edition. Walnut Creek, CA: C Places Inventory, Nomination Form.				
4 ARCHITECTURAL DESCRIP	PTION & INTEGRITY						
Building Type and/or Style: 2-Pa Additions: □ none ☑ minor □ Number of associated outbuildin General Condition of Exterior M	I major (describe below) Angs and/or structures:		No. Stories: 2 ninor □ major (describe below) #; □ structure(s), #				

Researcher/Organization: Preservation Solutions/Park City Municipal Corporation Date: 12-2008

☑ Good (Well maintained with no serious problems apparent.)
☐ Fair (Some problems are apparent. Describe the problems.):
☐ Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.):
☐ Uninhabitable/Ruin
Materials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. Describe the materials.): Foundation: Concrete.
Walls: Brick with wooden cornice.
Roof: Flat roof form.
Windows/Doors: Double-hung sash type with half-round transoms beneath brick hoods and large display windows (two) alternating with entry doors (three) all with transom windows.
Essential Historical Form: ☑ Retains ☐ Does Not Retain, due to:
Location: ☑ Original Location ☐ Moved (date) Original Location:
Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including datesknown or estimatedwhen alterations were made): The two-story brick 2-part block has been altered, but not significantly. The storefront originally had a center recessed entry door flanked by two large fixed casement display windows and doors on either end of the display windows. The center storefront was enframed within the larger storefront with square piers, but now the piers have been expanded and are equal width. The changes do not significantly impact the site's original design character.
Setting (The physical environmentnatural or manmadeof a historic site. Describe the setting and how it has changed over time.): The setting is typical of a mining era commercial core; buildings are located adjacent to one another and abut the sidewalk or street edge.
Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): The physical evidence from the period that defines this as a typical Park City mining era commercial building are the simple methods of construction, the use of rick, the recessed entrance and display windows, transom windows, the restrained ornamentation, and the plain finishes.
Feeling (Describe the property's historic character.): The physical elements of the site, in combination, convey a sense of the commercial activity in a western mining town of the late nineteenth and early twentieth centuries.
Association (Describe the link between the important historic era or person and the property.): The two-part block is one of the most common commercial building types constructed in Park City during the mining era.
This site was listed as a contributing building on the National Register of Historic Places in 1979 as part of the <i>Park City Main Street Historic District</i> . It was built within the historic period (1868-1929), is associated with the mining era, and retains its historic integrity. As a result, it meets the criteria set forth in LMC Chapter 15-11 for designation as a Landmark Site.
5 SIGNIFICANCE
Architect: ☑ Not Known ☐ Known: (source:) Date of Construction: c. 1917 ¹
Builder: ☑ Not Known ☐ Known: (source:)
The site must represent an important part of the history or architecture of the community. A site need only be significant under one of the three areas listed below:

¹ Notarianni, page 72.

							_		
1	١. ا	ш	ıct	1	rı	\sim	⊢ 1	ra	•
			ıoı	·	ш		_	а	١

- ☐ Settlement & Mining Boom Era (1868-1893)
- ☑ Mature Mining Era (1894-1930)
- ☐ Mining Decline & Emergence of Recreation Industry (1931-1962)

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's commercial buildings represent the best remaining metal mining town business district in the state. The buildings along Main Street, in particular, provide important documentation of the commercial character of mining towns of that period, including the range of building materials, building types, and architectural styles. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining business district².

- 2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):
- 3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.

Photo No. 1: East elevation. Camera facing west, 2006.

Photo No. 2: Southeast oblique. Camera facing northwest, 1995.

Photo No. 3: Southeast oblique. Camera facing northwest, tax photo.


Park City Historical Society & Museum has an extensive library of historic photographs; time constraints did not permit review of available historic photographs for this report.

² From "Park City Main Street Historic District" written by Philip Notarianni, 1979 and "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.

013	ESSENTIAL FIXTURES	No	Cost	T _{C==}	015 OTHER BUILDING	Each	015	OTHER			Each	T -
	PLUMBING	No.	Each		FEATURES Contd	or Cost		FEATURE			or S.F.	Cost
01	(2 3 4 5) Model () (2) (3) (4)			Ser E	4 x4 = 16 SECIO	JD 4 10 61	14	+ Interior	and the second	nts	0.7.	+
02	Water Closet	2	108		3 x 10 = 50 S.F.	20 160	15	- Overhe	ad Door			1
03	Lavatory	2	146	272			16	- Footing				1
04	Bathtub W/Shower	1	-	255	x =S.F, x =S.F,		11/	— Concre	te Floor		-	-
05	Bathtub W/O Shower Ceramic Tile Recess	-	-	90	08 Breezeways & Carports		1			015 TOTAL	1	3674
07	Kitchen Sink	+	-	166	- This is the state of the stat		016	SPECIAL	FEATU			
08	Laundry Tub			1	s							
3423	Shower Stall	_	т —	T247	x = S.F.		-		-		-	-
09	Ceramic Tile \	1		302	09 Storage Wall Only		1	1.	L. Carl		+	+
10	Metal Ceramic Tile Wainscote	-	-		Wood L.F.			-11			+	+
12	Water Heater	l		208	Brick 🗆L.F.							
13	Garbage Disposal				10 Garage (Att.) (Det.)		_		- 1		-	-
14	Sump Pump Floor Drain	-	-	21	(Bsmt.) (Built-in see 018-07)		17				-	
15	City Water Connection	1	-	200	11 Model (1) (2) (3) (4)				167			
17	City Sewer Connection	1		300	12 (F)rame (M)asonry				53			
18	Septic System				13 (1) car (1½) car		100	15h				
19	Well System	_	-		(2) car				W. L. F. E.	2000	United the all	e sign em
	Other 013 TOTAL	_	4	2250			1	Sec. 25.00		016 TOTAL	25	10000
014	ESSENTIAL FIXTURES	L.F.	Unit		017 OTHER IMPROVEMENTS	1-4	-		A. h	a service de la constante		-
	BUILT-INS	No.	Cant	Cost		ff. Size	Area	Cost	Cost	Depreciation Rating Fact		Depr.
	Kitchen Cabinets		<u> </u>	T-23	TC576A	'de T		Pacion	- 11	[Nating Fact	Dr 1	aiue
01	Model (1) (2) (3) (4)			1: 4111	TC574B			-/			7	
02	Cabinets are Sftwd. Under			1244								
03	Hrdwd. Set-In Range	V	-	lex								
05	Built-In Oven	1			-			-		-	1	
06	Cooktop	V		ex				-			-	
07	Hood and Fan	1		104	Conc. Tiel Work. Extensive				one 🗌			
08	Kitchen Vent Fan Dishwasher Built-In	-	+	1	Landscape: Extensive A	erage 🗌 Sparse	ly 🗆	None 🗆			-	
10	Vanity Cabinets	2	150	300	Sprinkling System % Fence: Ext. Wood or Mason	v □ Ava. Wood	d or V	Wire M	in Was	d or Wire	-	
11	Medicine Cabinet	2		52				·•		TOTAL		
12	Bathroom Vent Fan			1	018 REPLACEMENT COST N		019			& FMV		·
13	Bathroom Heater Sliding Glass Doors	_		-	SF\$ MULT LV. A		-	Less Physic				
15	Water Softener				01 Sec. A 13,99 ×1.13 × 5	31 8,390	02	RCN. Less		& Maint. (F-I)		
	Intercom System				03 Plumbing (013)	2,250	04		Strategic Control	CONTRACTOR AND ADDRESS OF THE PARTY OF THE P	_	
16					04 Built-ins (014)	1,700	05	RCN. Less	Phy. & F	Funct. Dep.		
17	AM/FM FIREPLACE				05 Other Bldg. Features (015)	3.670	06	Dep. Val. o			+ -	
18	Model (1) (2) (3) (4)				06 Special Bldg. Features (016 07 Less Ded. (B1 Guar. &		07	Total Imp. Less Econo				
19	1 Story				Unfinished Area)		09	FMV. of Blo				
20	1 1/2 or 2 Story + W/Fdn. in Bsmt.	-			08 Total 01 through 07	16,010	10	Cost/Sq. F		f 09 ()		
21	+ W/Roughed in	-			09 Time - Location Multiplier	x 1.25	11	FMV. of La			+	
23	+ W/Addn. Fireplace				Funct. Obs. 4405-78	20,013	12	FMV. of Pro	operty		-	
24	+ W/Look-Through				Funct. Obs. 4005-78		111			1144		
25 26	+ Heatilator Metal Fireplace (Inc.	140.00		لسل	P.S.			MIDE	•			
26	Chimney	SAR			E.S.		/	₹ W.				
	Other				C.C.		-1	1-1-1-1		+ +	19	
	014 TOTAL		Each	1,700			18		Land			1
015	OTHER BUILDING		or	Cost	and the same of the same and the same of t	17	Ť					
	(12345)		S.F.					1				
01	Attics Unfinished							In the	1017			
02	Finished P 17 x 30 = 510 S.F.		270	1913		14						
	xx=S.F.	<i>E</i> :	3,15	11413		1 1 2	30		11.1			
03	Dormers Unfinished		1		retained test	ST `					-	
04	Finished 🗆		115									Street,
	=			1								ACTO
	+=			1								
	x+=		_	+ 1		3	!	4×4	1-11			1
05				-	1	7 -	-	dwlo				
*	Model (1) 1(2) (3) (4)		3.00	1530	30H			70.00		1-21-11		
	17.x30 = 510 s.f.			-							0.2	
	x = S.F.		-	-		1 13						
			_	-						1		
06	Bsmt. Entry (1/2) or											
06	(F) ull Depth Entry Hood											

2.0

	di in		Deriai I	diliber				.,
owners Na	me First Se	aurit	Ba	nk	_		-	
Location =	lot 2 seh	10 PC	<u> </u>				oT.	
Kind of Bl	dg. BONK		_ St. 1	No. 40	51	10 Main	5/	
								x %
	Dimensions	Sq.		Factor		Totals	-	Totals
2	x x	10	00		s /	4833	\$	
	x x	,						
	x x							
Att. Gar.	C.Px	Flr.	Walls	Cl		()		
	Description	The second second				Additions		Additions
4 900	-Stone	Cons	-	Cille			П	
	Bric			51118			-	
Ext. Walls	3 hed	7501	PR	/		10		
					-	Kearp 8 -	60	1
	Small Me					//	10	1
	all Med .					/	П	
	Front			_			H	
				_	7		П	
	-			/			П	
		1			_		П	
Ext. Base.	Entry			2.90	a	792	H	
		34 Full		loor Con		.,.		
			1/				H	
	Apt Rms		X					
Attic Room	ns Fin.						H	-6
	Class /	_ Tub		Trays				
Plumbing	Wtr. Sftr.	Shr Shr	St	O.T.				
	Dishwasher	/5	Garbage	Disp.		393		
Heat-Stov	re н.а	/	1					
	Gas Coal			1		ine		
	- Full			1				
Finish—Fi	r. Hd. W	d	Pa	nel				
	Hd. V							
	Mar							
	lsWain			Floors				
	sh-Wood D				1			
	Metal							
	beers 4					610	Flo	1
Sof-Ju Bot	us 9 large 30,	yed 60	Small	9		1680		
Night	posit Bat					1600		
Total Addi	A					5075	-	
Year Buil	.0/	1.1001	D			19908		
and the same of			The same of the same of	ement Cost		6171		
1967 fur		-		scence 3/		13737		
Inf. by	Owner - <u>Tenant</u> Neighbor - Recor	d - Est.	The second	ld. Value		The second second		
		-	Conv. 1	olimina ne		x.47		
		cement						
	0	E 65		1 2 60 4 5				*
			, Less D	epreciatio	n		*	
Total Valu	ue from reverse si	111						
-				ilding Val		\$	4 0	1968
Appraised	① //- /3		196	By /2	33	DEC	LV	1968
Appraisad				By		6 50		1328



RESIDENTIAL OUT BUILDINGS	Age	Size	Area	Fac- tor	Cost	Conv. Fac.	Adj. Cost	Depr. Value
		x				.47		- 3
Ligure as I Stry Beldy		x				.47		
require as 1 to age of		x				.47		
		x				.47		
		x				.47		
		x				.47		
Size x Age	. x	% Depr	тт	-	-			
REMARKS								



PG .146



