HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION			(
Name of Property:							
Address: 436 MAIN ST			AKA:				
City, County: Park City, Summit	County, Utah		Tax Number:	436-MAIN-1			
Current Owner Name: MOUNTAIN SEAS DEVELOPMENT LTD Parent Parcel(s): PC-294 Current Owner Address: PO BOX 680844, PARK CITY, UT 84068-0844 Legal Description (include acreage): LOT 1, 436 MAIN STREET SUBDIVISION, 0.06 AC							
2 STATUS/USE							
Property Category ☑ building(s), main □ building(s), attached □ building(s), detached □ building(s), public □ building(s), accessory □ structure(s)	Evaluation* ☑ Landmark Site ☐ Significant Site ☐ Not Historic *National Register of H ☑ listed (date: 03/07/1		Partial s: □ ineligible				
3 DOCUMENTATION							
Blaes, Dina & Beatrice Lufkin. "Fina	□ abstract of t □ tax card □ original build □ sewer perm □ Sanborn Ma □ obituary ind □ city directoricy □ census recount □ biographica □ newspapers bks, articles, interviews, al Report." Park City Histor	rd □ personal interviews al building permit □ Utah Hist. Research Center permit □ USHS Preservation Files orn Maps □ USHS Architects File ry index □ LDS Family History Library rectories/gazetteers □ Park City Hist. Soc/Museum s records □ university library(ies): phical encyclopedias □ other:					
Carter, Thomas and Goss, Peter. <i>Utah's Historic Architecture, 1847-1940: a Guide.</i> Salt Lake City, Utah: University of Utah Graduate School of Architecture and Utah State Historical Society, 1991. Longstreth, Richard. <i>The Buildings of Main Street; A Guide to Commercial Architecture.</i> Updated edition. Walnut Creek, CA: Alta Mira Press, a division of Rowman & Littlefield Publishers, Inc., 2000. Notarianni, Philip F., "Park City Main Street Historic District." National Register of Historic Places Inventory, Nomination Form. 1979. Roberts, Allen. "Final Report." Park City Reconnaissance Level Survey. Salt Lake City: 1995.							
4 ARCHITECTURAL DESCRIPTION & INTEGRITY							
Building Type and/or Style: 1-Part Block Additions: □ none ☑ minor □ major (describe below) Alterations: □ none □ minor ☑ major (describe below) Number of associated outbuildings and/or structures: □ accessory building(s), #; □ structure(s), # General Condition of Exterior Materials:							

Researcher/Organization: Preservation Solutions/Park City Municipal Corporation Date: 12-2008

☑ Good (Well maintained with no serious problems apparent.)
☐ Fair (Some problems are apparent. Describe the problems.):
☐ Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.):
☐ Uninhabitable/Ruin
Materials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. Describe the materials.): Foundation: Tax cards indicate a concrete foundation.
Walls: Wooden siding decorative cornice elements.
Roof: Flat roof.
Windows/Doors: large fixed casement single-pane display windows with transoms and recessed entry door with transoms.
Essential Historical Form: ☑ Retains ☐ Does Not Retain, due to:
Location: ☑ Original Location ☐ Moved (date) Original Location:
Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including datesknown or estimatedwhen alterations were made): The one-story frame 1-part block was damaged by fire in 1993. Previous surveys have indicated this was a new building, but based on photographs and records in the Building Department filespermit filesthe façade was only partially damaged by the fire. Most of the façade material was repaired when the building was reconstructed following the fire. The changes are minor and serve to restore the site's original design character.
Setting (The physical environmentnatural or manmadeof a historic site. Describe the setting and how it has changed over time.): The setting is typical of a mining era commercial core; buildings are located adjacent to one another and abut the sidewalk or street edge.
Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): The physical evidence from the period that defines this as a typical Park City mining era commercial building are the simple methods of construction, the use of non-beveled (drop-novelty) wood siding, the recessed entrance and large display windows, transom windows, the restrained ornamentationsimple cornice and cornice bracketsand the plain finishes.
Feeling (Describe the property's historic character.): The physical elements of the site, in combination, convey a sense of the commercial activity in a western mining town of the late nineteenth and early twentieth centuries.
Association (Describe the link between the important historic era or person and the property.): The one-part block is one of the most common commercial building types constructed in Park City during the mining era.
This site was listed on the National Register of Historic Places in 1979 as part of the <i>Park City Main Street Historic District</i> . It was built within the historic period (1868-1929), is associated with the mining era, and retains its historic integrity. As a result, it meets the criteria set forth in LMC Chapter 15-11 for designation as a Landmark Site.
5 SIGNIFICANCE
Architect: ☑ Not Known ☐ Known: (source:) Date of Construction: c. 1898 ¹
Builder: ☑ Not Known ☐ Known: (source:)
The site must represent an important part of the history or architecture of the community. A site need only be significant under one of the three areas listed below:

¹ Summit County Recorder.

1	ш	0+1	oric		2
- 1	п	1510) (:	_	17

- ☐ Settlement & Mining Boom Era (1868-1893)
- ☑ Mature Mining Era (1894-1930)
- ☐ Mining Decline & Emergence of Recreation Industry (1931-1962)

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's commercial buildings represent the best remaining metal mining town business district in the state. The buildings along Main Street, in particular, provide important documentation of the commercial character of mining towns of that period, including the range of building materials, building types, and architectural styles. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining business district².

- 2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):
- 3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.

Photo No. 1: Northwest oblique. Camera facing southeast, 2008.

Photo No. 2: West elevation. Camera facing east, 2008.

Photo No. 3: Southwest oblique. Camera facing northeast, 2008.

Photo No. 4: West elevation. Camera facing east, 2006.

Photo No. 5: West elevation. Camera facing east, 1995.

² From "Park City Main Street Historic District" written by Philip Notarianni, 1979 and "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.

Location	n				
Kind o	of Bldg. Stone				-
Class_	Rms	Type 123 4.	Cost \$		X%
Stories	Dimensions	Cu. Ft.	Sq. Ft.	Factor	Totals
1	x x	Electrical designation of the second	1260	9	\$ 2355
	x x				
	x x				
Att. G	ar. x Flr.	Walls	1	Roof	
Founda	tion—Stone	Conc.	None		
Ext. W	Valls Side	a			
Insulati	on- FloorsWal	ls			
		MtlRR			
Dormer	s- Small Med	Large	VA CONTRACTOR		
	Small Med				
	- Front				
	Lean 6×15		@ 100	90	
	nt Entr.		@		
Planters			@ (:xxxx)		
Cellar-I	Bsmt. — 1/4 1/3 1/2 2/3 3/4	Full Floor_	dust,	329	
	Apt Rooms Fi	V	n		
	Rooms Fin.	Un(in			
	(Class 1	TubT	rays	Plants.	
DI 1.	BasinS		oilet		
Plumbi	Urls Dishwasher		Shr	255	
Heat— Oil_					
	ondHd.				
	Fir Hd. Wo	1	er		
	ts Mantels_				
	WallsWainsco	Fixt.	1		
	Sash— WoodMet		1		
			_ Sasii		
Metal	Awnings		The same		THE REPORT OF THE PARTY OF THE
A			-		
-					
				674	The state of the s
-	Additions Built \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Parada	ction Value		\$ 3029
Tear E	Age	Depr. C	col 2 3 4	5 6 30 %	
	(Owner - Tenant -		al. Minus D		909
Inf. by	Neighbor - Record		or Rem.	%	
-	el Year Est. Cost	The state of the s	dg. Value		\$
	- ClassDep				
	Floor				
Size-	xAge	Cost		x%	
Other_			are open appear		The state of the s
			Total Buildir	ng Value	\$
Apprai	sed Doe 12	3 19 57	By\	331	
- was farent		The state of the s	The state of the s		


	Leanto	
	15 2 0	
	6	
	/	
	84	
	65	
	24	
	33h	
emarks:		
	16年5月18日本	
		THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW

TC . 74 REV. 54 50M. 15M

STATE OF UTAH - STATE TAX COMMISSION



Owners	Name								
Location				-	-			.,	
Kind of Bldg. store St. No. 436 No. Main St.									
Class					. X %				
Stories	Dimensions	s Sq	. Ft.	Factor		Totals	1_	Totals	
1	x x	/3	20		\$	4373	8		
	x x	-				/-			
	x x			4					
Att. Gar	.—C.Px_	Flr	_ Walls_	C1					
	Descri	ption of Build	dings	18		Additions		Additions	
Foundat	ion—Stone	Conc.	L	_Sills					
Ext. Wa	11s Sechie	1							
Roof Ty	pe # lat	Mtl	Ba	۷					
	—Small								
	mall M					,			
	Front								
				_		1			
				_	-				
				_					
Cellar-B	e. Entry smt. — 1/3 20 \$	4 % % Full	.96 _F	loor work	1	1267			
	ar								
	t-Apt	Rms	Fin. Rn	ns.					
	oms Fin					-			
							1	Reappy	
	Basin	/ Sink_	То	ilet /		393		8-16-79	
Plumbing Class					_	273	1	1952	
	Dishwashe	r	Garbage :	Disp		175	-		
Heat—St	ove H.A	FA HW	5mg	Tunt	>	675			
Oil	Gas Coa l. — Full	al Pipele	SS N E	adiant	5		+		
Air Cond	l. — Full —		Zone _		=		+		
Finish—	Fir. Hd				-		+		
Floor-F		d. Wd					H		
	-						+		
Tile -Wa	alls	Wainscot	F	loors	-		+		
	ash—Wood D.						+		
Awnings	— Metal	F	iberglass		-		+		
		(1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-							
						2235	-		
Total Ad						2333			
Year Bu	ilt. 1898	Avg. 1./898	Replacer	ment Cost	- 1	6708			
		Age 2.	Obsolesc	ence					
Inf. by	Owner - Tena Neighbor - Re	nt	Adj. Bld	l. Value					
	(Lieighbor - Re	cord - Est.	Conv. Fa	actor		x.47			
	Λ	eplacement (_			5		
	U D	epreciation (column 1	2 3 4 5	6				
1940 Base Cost, Less Depreciation									
Total Va	lue from revers	e side							
		T	otal Buil	ding Valu	e	S DEC 1	0	1968	
Appraise	d 10-17	7	16.8	_ By 13	33	3	- 6	1220	
Appraised ②									



			24	, ' 9	etTu	2			
RESIDENTI	AL OUT BUILDINGS	Age	Size	Area	Fac- tor	Cost	Conv. Fac.	Adj. Cost	Depr. Value
100			x				.47		
			x				.47		
			x				.47		
			x				.47	-1	
			x				.47		
			x				.47		
Garage — Cla	nss Depr. 2%	3% _							
Cars	FloorWal	ls	Roof		D	oors			
Size	_ x Age		_ Cost			x 47 %	,		
	1940 Base Cost	x	_% Depr.						
				То	tal				
REMARKS _									

TC-74 REV. 61

STATE OF UTAH - STATE TAX COMMISSION

Melva Garcia 396 Smalley Ave. Hayward, CA 94541

PC 294 PtL9B25 HQC27 IQC-M55-425 649 XWD319

PC 294 N 24 ft lot 9 Blk 23 Park City Survey

			PARCEI	NO.
			Her 24x75	FRONTAGE OR AREA
			1006 200Sf	DEPTH FACTOR
			2005f	RATE
TOTAL ASSESSED VALUE				CORNER INFLU- ENCE
VALUE VALUE				RATE
2660	985 985		4800	VALUE









