

HISTORIC SITES INVENTORY HISTORIC SITE FORM

PARK CITY MUNICIPAL CORPORATION



IDENTIFICATION

STATUS / USE

Property Name (if any): House at 569 Park Avenue

Address: 569 Park Avenue

Date of Construction: c. 1917 City, County: Park City, Summit County, Utah

Architect/Builder, if known: unknown Tax Number: PC-82

Current Owner: William A. and Janet Kershaw, et. al.

Architectural Style: bungalow type, Victorian Eclectic style

Legal Description (include acreage): LOTS 17 & 18 BLK 5 PARK CITY SURVEY

Original Use: single dwelling	Current Use: single dwelling			
Property Type:	National Register of Historic Places:		Evaluation:	
Building	☐ Eligible		Landmark	< Site
Structure	Ineligible		Significan	t Site
Site	☐ Listed, Date:		☐ Non Histo	ric
DOCUMENTATION				
Photographs:	Research Sources:			
Tax Photos	Sanborn Maps	City/ County Histor	ies 🗆 Ne	ewspapers
Prints:	☐ tax Card	☐ Personal Interviews	Ot	her:
Historic	Census Records	Park City Museum		
DESCRIPTION				

No. Stories: 1					
Number of As	sociated Structures:	Accessory buildi	ng(s).#	Structure	(s).#
Condition:	Good	Fair	Poor	Uninhabit	able/Ruin
Location:	Original location	☐ Moved (Date:	original loc	ation:)
Materials: (De	scribe the visible mate	rials)			
Exterior Walls:	clapboard siding				
Foundation: c	oncrete				
Roof: wood sh	ningles				
Windows/Doo	rs: slider windows (typi	cal) and glazed wood	I front door with	n wooden trim	
Additions:	Major	☐ Minor	None		
Alterations:	Major	☐ Minor	None		
Describe Add	itions/ Alterations (Date	es):			
Essential Histo	oric Form: Retains			Does Not Retain	
NARRATIVE D	ESCRIPTION OF PRO	PERTY			
`		•	•		a general description of
	ncluding the overall sha associated structures; i	•			shape of roof; identify and
describe arry t	associated structures,	dentity drip known ex	terior additions	and/or alteration	10.)
SIGNIFICANO	E				
Historic Era:					
Settlement	& Mining Boom Era (1	868-1893)			
■ Mature Mir	ning Era (1894-1930)				
☐ Mining Dec	line & Emergence of R	ecreation Industry (19	931-1962)		
Narrative Stat	ement of Significance:				
(Briefly descri	be those characteristic	s by which this prope	rty may be con	sidered historica	lly significant.)

By the 1890s, Park City was a bona fide mining town, with a railroad station,

post office, fire department, and growing school system. While individuals lost and gained jobs based on fluctuating silver prices, the mining industry was relatively stable in Park City through the 1920s. The Great Fire of 1898 proved the strength of the town: while Main Street was almost completely levelled and sustained over \$1,000,000 in damages, most of the buildings were rebuilt by 1900. Unlike other fire ravaged western mining towns, which often went permanently bust over similar blazes, the demand for Park City silver caused a rapid rebuilding of the business district. Park City survived the Spanish Flu Epidemic, World War I, and Prohibition mostly unscathed, boasting over 4,000 residents in the 1930 United States Census.

REFERENCES

Carter, Thomas and Peter Goss. Utah's Historic Architecture, 1847-1940. Salt Lake City: Center for Architectural Studies, Graduate School of Architecture, University of Utah and Utah State Historical Society, 1988. Hampshire, David, Martha Sonntag Bradley and Allen Roberts. A History of Summit County. Coalville, UT: Summit County Commission, 1998. National Register of Historic Places. Park City Main Street Historic District. Park City, Utah, National Register #79002511. Peterson, Marie Ross and Mary M. Pearson. Echoes of Yesterday: Summit County Centennial History. Salt Lake City: Daughters of Utah Pioneers, 1947. Randall, Deborah Lyn. Park City, Utah: An Architectural History of Mining Town Housing, 1869 to 1907. Master of Arts thesis, University of Utah, 1985. Thompson, George A., and Fraser Buck. Treasure Mountain Home: Park City Revisited. Salt Lake City: Dream Garden Press, 1993.

(Provide several clear historical and current photos of the property as well as locational maps indicating the location of the property in relation to streets or other widely recognized features.)




Photo No. 1: Northeast oblique. Camera facing southwest. November 2014.



Photo No. 2: East elevation. Camera facing west. November 2014.




Photo No. 3: Southeast oblique. Camera facing northwest. November 2014.





569 Park Avenue


1889

Sanborn Map History









EVALUATION FOR HISTORIC POTENTIAL FILES

		51			
(enter date	in blanks)				
(CIII)		evaluation m	ade	9	
7	Encoded .	×			3,
alanlah	Added to co	untu list			
2121100					•
-	Added to ye	early record			
Asso Asso Sig. Other ALTERED: None Mind	eciated Historiciated Historic	ric Event ric Theme	Signific Signific Signific	ructed	ction Type
EVALUATION					
EVALORIZOR	•			No Evaluat	ion
(A) -	Significant Contributory	_ Out of _ Non-cor	ntributory	NO LUCIALIS	
			COMMENTS		
	(include a	ny relevant in	nformation to	explain eva	luation)
				* *	
					٠.
		,			
					1*
				* *	
	*	(*)	Evaluator	``	
			Date:		

Researcher:

Philip F. Notarianni

Date:

August, 1978

Site No. SU-10-144

Utah State Historical Society Historic Preservation Research Office

Structure/Site Information Form

IDENTIFICATION —	Street Address: Name of Structure: Present Owner: Owner Address:	Donald R. Neil et. a		60	Plat ^{PC} T. F UTM: Tax #:		t 17–18
2	Original Owner:	1.0. Box Tark Oreyk	Construction		Demolitic	n Date:	
AGE/CONDITION/USE	Original Use: Present Use: Single-Family Multi-Family Public Commercial	residential Park Industrial Agricultural	□ Vacant □ Religiou □ Other	ıs	Occupa	ants:	
AGE/C	Building Condition: Excellent Good Deteriorated	□ Site □ Ruins	Integrity: Unaltered Minor Altera Major Altera				
STATUS C	Preliminary Evaluation Significant Contributory Of Not Contributory Intrusion	on:				e	
DOCUMENTATION P	Photography: Date of Slides: 11/7 Views: Front Side Be Research Sources: Abstract of Title Plat Records Plat Map Tax Card & Photo Building Permit Sewer Permit Sanborn Maps		Views: pedias	of Photographs:	ives		

Bibliographical References (books, articles, records, interviews, old photographs and maps, etc.):

Summit County Recorder and Assessor Records, Summit County Courthouse, Coalville, Utah. Sanborn Map, Park City, Utah, 1907.

-				
5	Architect/Builder:	unknown		originally a residential
ЭE (Building Materials:	wood	Building Type/Style:	bungalow.
ECTUR	Description of phys	ical appearance & sign (Include additions, alterations,	nificant architectural feat ancillary structures, and landscaping	ures: if applicable)

Presently, a one-story frame with a gable roof, and alumunum siding. Tax photos indicate a "major" alteration, since the structure originally appeared as a frame bungalow with hip roof.

6	Statement of Histori	cal Significance:		(9) - ·	_
ORY (☐ Aboriginal Americans ☐ Agriculture ☐ Architecture	☐ Communication☐ Conservation☐ Education☐	☐ Military☐ Mining☐ Minority Groups	☐ Religion ☐ Science ☐ Socio-Humanitarian	
HIST	☐ The Arts ☐ Commerce	□ Exploration/Settlement□ Industry	□ Political □ Recreation	□ Transportation	

Names associated with the structure:

- 1. Thomas M. Stringer,
- 2. Issac L. Osborne.
- 3. 1919- mortgaged from Alice E. Deighton to Samuel B. Dunn.
- 4. 1924, Herman Hethke.

Site No. <u>SU-10-144</u>

Researcher:

Philip F. Notarianni August,1978

Date:

Utah State Historical Society Historic Preservation Research Office

Structure/Site Information Form

1											
O	Street Address:	569 Park	Ave.							5 Lot 17	-18
CAT	Name of Structu	re:						T.	R.	S.	_
Ħ	Present Owner:	Dona1d R.	Neil, et.al					UTN	۷:		
IDENTIFICATION	Owner Address	: P.O. Box	Park City,	Utah 8406	0			Tax	#:	PC-82	
2	Original Owner:			Constru	ction Da	ate: @192	23	Demo	lition	Date:	
	Original Use:	residenti	.a1								-
AGE/CONDITION/USE	Present Use: "Single-Family Multi-Family Public Commercial		□ Park □ Industrial □ Agricultural	□ Vaca □ Reli □ Othe	gious			Occ	upan	ts:	
AGE/0	Building Condit Excellent Good Deteriorated		□ Site □ Ruins	Integrity □ Unaltere □ Minor Al ® Major Al	d terations	complete	ely cl	hanged			
STATUS C	Preliminary Eva Significant Contributory Not Contributory Intrusion	lluation: (see desci	ription)		□ Na □ Na	al Registe ational Landma ational Registe ate Register	ark □ l er □ l				
DOCUMENTATION P	Photography: Date of Slides: Views: Front Source Research Source Plat Records Plat Records Plat Map Tax Card & Photo Building Permit Sewer Permit Sanborn Maps		☐ City Directories☐ Biographical End ☐ Obituary Index☐ County & City H☐ Personal Intervied☐ Newspapers	Vie cyclopedias istories		graphs: Side Real LDS Church LDS Genealo U of U Library BYU Library USU LIbrary SLC Library Other	Archives	s			

Bibliographical References (books, articles, records, interviews, old photographs and maps, etc.):

Summit County Recorder and Assessor Records, Summit County Courthouse, Coalville, Utah. Sanborn Map, Park City, Utah 1907.

5	Architect/Builder: unknown		1	
Ä	Building Materials: wood	Building Type/Style:	originally a	residential
ITECTUF	Description of physical appearance (Include additions, all	& significant architectural featerations, ancillary structures, and landscap	atures: ing if applicable)	bungalow.

ARCHI Presently, a one story frame with a gable roof, and aluminum siding. Tax photographs indicate a "major" alteration, since the structure originally appeared as a frame bungalow with a hip roof.

6	Statement of Histori	cal Significance:		
HISTORY	☐ Aboriginal Americans ☐ Agriculture ☐ Architecture ☐ The Arts ☐ Commerce	☐ Communication ☐ Conservation ☐ Education ☐ Exploration/Settlement ☐ Industry	□ Military□ Mining□ Minority Groups□ Political□ Recreation	☐ Religion☐ Science☐ Socio-Humanitarian☐ Transportation

Names associated with the structure:

- 1. Thomas M. Stringer.
 2. Issac L. Osborne.
 3. 1919-mortgaged from Alice E. Deighton to Samuel B. Dunn.
 4. 1924, Herman Hethke.