HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1	ID	(IT		CA	т		N
	ı	4 I I	IFI	\sim	١ı	v	v

Name of Property:

Address: 114 HILLSIDE AVE AKA: 114 Sandridge Road

City, County: Park City, Summit County, Utah Tax Number: PC-588

Current Owner Name: PETERSON DENNIS L TRUSTEE Parent Parcel(s):

Current Owner Address: 8937 N LARIAT RD, PARK CITY, UT 84098

Legal Description (include acreage): PARCEL 1: BEG AT A PT WH IS N 400 FT M/L & W 344 FT M/L FROM THE SE'LY COR OF SEC 16 T2SR4E SLBM SD PT BEING THE NW COR OF LOT 31 BLK 72 AMENDED PLAT OF PARK CITY SUMMIT COUNTY UTAH; SD PT IS ALSO DESC AS BEING N 40*41'44" W 527.58 FT FROM THE SE COR OF SD SEC 16; TH S 82*15' W 25.50 FT M/L ALONG AN EXISTING FENCE; TH S 5*27' E 52.0 FT M/L ALONG AN EXISTING FENCE TO A PT 2 FT M/L BEYOND SD FENCE LINE EXTENDED; TH S 68*58' E 7.80 FT M/L ALONG A LINE WH IS 2 FT M/L W OF AN EXISTING FENCE LINE; TH S 2*15'42" E 40.60 FT ALONG A LINE WH IS 3.0 FT W OF AN EXISTING FENCE WH FENCE IS W OF THE HOUSE ON THE SUBJECT PROPERTY; TH N 84*06'42" E 42.0 FT ALONG A LINE WH IS 1 TO 2 FT OUTSIDE AN EXISTING FENCE; TH N 2*15'42" W 38.4 FT; TH N 12*19' W 59.45 FT ALONG A LINE WH IS 2 FT M/L OUTSIDE AN EXISTING FENCE: TH S 82*15' W 15.8 FT ALONG AN EXISTING WOOD FENCE TO THE PT OF BEG CONT 0.10 AC: PARCEL 2: A PORTION OF LOTS 31.32.33 & ALL OF LOTS 34 & 35 BLK 72 MILLSITE RESERVATION TO PARK CITY TOWNSITE; ACCORDING TO THE OFFICIAL PLAT THEREOF ON FILE & OF RECORD IN THE OFFICE OF THE RECORDER SUMMIT COUNTY UTAH LOCATED IN THE SE1/4 OF SEC 16 T2SR4E SLBM SD PARCEL BEING MORE PARTICULARLY DESC AS FOLLOWS: BEG AT THE NORTHERNMOST COR OF SD LOT 31 BLK 72 MILLSITE RESERVATION; TH ALONG THE E'LY BOUNDARY OF SD BLK 72 S 15*03'00" E 126.38 FT TO THE S'LY BOUNDARY OF SD LOT 35 BLK 72 MILLSITE RESERVATION; TH ALONG THE S'LY BOUNDARY OF SD LOT 35 S 66*29'00" W 12.47 FT TO THE W'LY BOUNDARY OF SD BLK 72; TH ALONG THE W'LY BOUNDARY OF SD BLK 72 N 23*31'00" W 51.35 FT TO A PT ON THE E'LY BOUNDARY OF A PARCEL OF LAND DESC IN A DEED RECORDED MAY 7, 2001 ENTRY #588448 BK 1369-422 ON FILE & OF RECORD IN THE OFFICE OF THE RECORDER SUMMIT COUNTY UTAH; TH ALONG SD BOUNDARY THE FOLLOWING THREE (3) COURSES: 1) N 02*15'42" W 9.66 FT; TH 2) N 12*19'00" W 59.45 FT; TH 3) S 82*15'00" W 15.64 FT TO A PT ON THE W'LY BOUNDARY OF SD BLK 72; TH ALONG THE W'LY BOUNDARY OF SD BLK 72 N 23*31'00" W 1.40 FT; TH N 80*58'45" E 4.27 FT; TH N 11*12'10" W 1.79 FT TO A PT ON THE N'LY BOUNDARY OF LOT 31 BLK 72 MILLSITE RESERVATION; TH ALONG THE N'LY BOUNDARY OF SD LOT 31 N 66*29'00" E 26.55 FT TO THE PT OF BEG CONT 2127 SQ FT (LESS ANY PORTION OF PARCEL 2 WH LIES WITHIN PARCEL 1) (LESS 27 SQ FT 1797-2003 PC-594) (LESS ANY PORTION LYING WITHIN THE MARSAC AVENUE RIGHT-OF-WAY/CHAMBERS STREET RIGHT-OF-WAY ROAD DEDICATION PLAT) BAL 0.14 AC

2 STATUS/USE			
Property Category ☑ building(s), main ☐ building(s), attached ☐ building(s), detached ☐ building(s), public	Evaluation* □ Landmark Site ☑ Significant Site □ Not Historic	<u>Reconstruction</u> Date: Permit #: □ Full □ Partial	<u>Use</u> Original Use: Residential Current Use: Residential
☑ building(s), accessory☐ structure(s)	*National Register of ☐ listed (date:)	Historic Places: ☑ ineligible	□ eligible
3 DOCUMENTATION			

Photos: Dates	Research Sources (check all sources							
□ tax photo:	☐ abstract of title	☑ city/county histories						
□ prints:	□ tax card	□ personal interviews						
☐ historic: c.	☐ original building permit	☐ Utah Hist. Research Center						
Drawings and Plans	☐ sewer permit	☐ USHS Preservation Files						
<u>Drawings and Plans</u> ☐ measured floor plans	✓ Sanborn Maps☐ obituary index	☐ USHS Architects File☐ LDS Family History Library						
☐ site sketch map	☐ city directories/gazetteers	☐ Park City Hist. Soc/Museum						
☐ Historic American Bldg. Survey	☐ census records	☐ university library(ies):						
☐ original plans:	☐ biographical encyclopedias	other:						
□ other:	□ newspapers	_ 00						
Bibliographical References (books, articles, interviews, etc.) Attach copies of all research notes and materials.								
Carter, Thomas and Goss, Peter. <i>Utah's H</i> University of Utah Graduate School of	t." Park City Historic Building Inventory. Salt listoric Architecture, 1847-1940: a Guide. Sa Architecture and Usas Natur Visitin Missald Sale	alt Lake City, Utah: ty, 1991.						
	to American Houses. New York: Alfred A. I connaissance Level Survey. Salt Lake City:							
	nces of Mining Boom Era, Park City - Thema							
Historic Places Inventory, Nomination I	Form. 1984.	•						
4 ARCHITECTURAL DESCRIPTION	& INTEGRITY							
Building Type and/or Style: Hall-Parlo	r type / Vernacular style	No. Stories: 1						
Additions: ☐ none ☑minor ☐ major	(describe below) Alterations: ☐ none ı	minor major (describe below)						
Number of associated outbuildings and	I/or structures: \square accessory building(s),	#1_;						
General Condition of Exterior Materials	:							
☑Good (Well maintained with no serious	problems apparent.)	☑Good (Well maintained with no serious problems apparent.)						
П Го:т /О								
☐ Fair (Some problems are apparent. De	escribe the problems.):							
	escribe the problems.): and constitute an imminent threat. Describe the pro	oblems.):						
		oblems.):						
☐ Poor (Major problems are apparent ar ☐ Uninhabitable/Ruin Materials (The physical elements that were co								
☐ Poor (Major problems are apparent ar ☐ Uninhabitable/Ruin Materials (The physical elements that were co- configuration. Describe the materials.):	nd constitute an imminent threat. Describe the pro	time in a particular pattern or						
☐ Poor (Major problems are apparent ar ☐ Uninhabitable/Ruin Materials (The physical elements that were co- configuration. Describe the materials.): Foundation: The 1968 tax card no	nd constitute an imminent threat. Describe the pro	time in a particular pattern or						
☐ Poor (Major problems are apparent ar ☐ Uninhabitable/Ruin Materials (The physical elements that were co- configuration. Describe the materials.): Foundation: The 1968 tax card no photographs and therefore its mate	and constitute an imminent threat. Describe the prombined or deposited during a particular period of tes a stone foundation. The foundation erial or existence cannot be verified.	time in a particular pattern or is not visible in the available						
☐ Poor (Major problems are apparent an ☐ Uninhabitable/Ruin Materials (The physical elements that were configuration. Describe the materials.): Foundation: The 1968 tax card no photographs and therefore its materials.	nd constitute an imminent threat. Describe the prombined or deposited during a particular period of tes a stone foundation. The foundation	time in a particular pattern or is not visible in the available s to retain the aluminum clapboard						
☐ Poor (Major problems are apparent ar ☐ Uninhabitable/Ruin Materials (The physical elements that were co configuration. Describe the materials.): Foundation: The 1968 tax card no photographs and therefore its mat Walls: The 1968 tax card mention siding and imitation stone facing h	mbined or deposited during a particular period of tes a stone foundation. The foundation erial or existence cannot be verified. It is aluminum siding. The house appears as been added to the lower wall surface	time in a particular pattern or is not visible in the available a to retain the aluminum clapboard es.						
☐ Poor (Major problems are apparent ar ☐ Uninhabitable/Ruin Materials (The physical elements that were co configuration. Describe the materials.): Foundation: The 1968 tax card no photographs and therefore its mat Walls: The 1968 tax card mention siding and imitation stone facing h	and constitute an imminent threat. Describe the pro- mbined or deposited during a particular period of tes a stone foundation. The foundation erial or existence cannot be verified.	time in a particular pattern or is not visible in the available a to retain the aluminum clapboard es.						
□ Poor (Major problems are apparent are □ Uninhabitable/Ruin Materials (The physical elements that were conconfiguration. Describe the materials.): Foundation: The 1968 tax card no photographs and therefore its materials. Walls: The 1968 tax card mentions siding and imitation stone facing has a solution.	mbined or deposited during a particular period of tes a stone foundation. The foundation erial or existence cannot be verified. It is aluminum siding. The house appears as been added to the lower wall surface the both sheathed in standing seam metal ows appear to be aluminum sliders. The	is not visible in the available to retain the aluminum clapboard es.						
□ Poor (Major problems are apparent are □ Uninhabitable/Ruin Materials (The physical elements that were co- configuration. Describe the materials.): Foundation: The 1968 tax card no photographs and therefore its mate Walls: The 1968 tax card mention siding and imitation stone facing h Roof: The porch and the house are Windows/Doors: The visible windo- cannot be determined from the average of the control of the second control of the c	mbined or deposited during a particular period of tes a stone foundation. The foundation erial or existence cannot be verified. It is aluminum siding. The house appears as been added to the lower wall surface the both sheathed in standing seam metal ows appear to be aluminum sliders. The ailable photographs.	time in a particular pattern or is not visible in the available to retain the aluminum clapboard es. al roofing materials. e style and materials of the door						
□ Poor (Major problems are apparent are □ Uninhabitable/Ruin Materials (The physical elements that were configuration. Describe the materials.): Foundation: The 1968 tax card no photographs and therefore its materials. Walls: The 1968 tax card mentions siding and imitation stone facing has a windows/Doors: The visible windows/Doors: The visible windows/Doors: The visible windows/Doors: The 1968 tax card limprovements: The 1968 tax card	mbined or deposited during a particular period of tes a stone foundation. The foundation erial or existence cannot be verified. It is aluminum siding. The house appears as been added to the lower wall surface the both sheathed in standing seam metal ows appear to be aluminum sliders. The ailable photographs.	time in a particular pattern or is not visible in the available to retain the aluminum clapboard es. al roofing materials. e style and materials of the door						
□ Poor (Major problems are apparent an □ Uninhabitable/Ruin Materials (The physical elements that were conconfiguration. Describe the materials.): Foundation: The 1968 tax card no photographs and therefore its materials. Walls: The 1968 tax card mentions siding and imitation stone facing has a windows/Doors: The visible windows/Doors: The visible windows/Doors: The visible windows/Doors: The 1968 tax card therefore its material or existence. Essential Historical Form: ☑ Retains	mbined or deposited during a particular period of tes a stone foundation. The foundation erial or existence cannot be verified. It is aluminum siding. The house appears as been added to the lower wall surface the both sheathed in standing seam metal ows appear to be aluminum sliders. The ailable photographs. It is not visible in cannot be verified.	time in a particular pattern or is not visible in the available a to retain the aluminum clapboard es. al roofing materials. e style and materials of the door in the available photographs and						

Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including dates--known or estimated--when alterations were made):

This house is a single story frame side-gabled hall-parlor house with a crosswing and a rear shed extension with a shed-roofed open front porch. The porch roof has square wooden supports and the porch railing is a picket fence. The porch was most likely added c. 1964.

Setting (The physical environment--natural or manmade--of a historic site. Describe the setting and how it has changed over time.):

The yard is informally landscaped with deciduous trees. The c. 1940 tax photo doesn't show any vegetation. The surrounding area in the 2006 photographs appears to be vacant hillsides with natural vegetation.

Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): The physical evidence from the period that defines the typical Park City mining era home-simple methods of construction, the use of non-beveled (drop-novelty) wood siding, plan type, simple roof form, informal landscaping, restrained ornamentation, and plain finishes--have been altered and, therefore, lost. The wood siding is most likely still found under the aluminum siding.

Feeling (Describe the property's historic character.): The physical elements of the site, in combination, do not effectively convey a sense of life in a western mining town of the late nineteenth and early twentieth centuries.

Association (Describe the link between the important historic era or person and the property.): The Hall-Parlor house form is the earliest type to be built in Park City and one of the three most common house types built in Park City during the mining era; however, the extent of the alterations to the main building diminishes its association with the past.

The extent and cumulative effect of alterations to the site render it ineligible for listing in the National Register of Historic Places.

5 SIGNIFICANCE		
Architect: ☑ Not Known ☐ Known: (source:)	Date of Construction: c. 1904
Builder: ☑ Not Known ☐ Known: (s	source:)	
The site must represent an important pa significant under one of the three areas	art of the history or architecture of the com listed below:	munity. A site need only be
Historic Era: Settlement & Mining Boom Era (18 Mature Mining Era (1894-1930) Mining Decline & Emergence of Re	,	
Park City was the center of one of t	the ton three metal mining districts in the	state during Utah's mining

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's houses are the largest and bestpreserved group of residential buildings in a metal mining town in Utah. As such, they provide the most complete documentation of the residential character of mining towns of that period, including their settlement patterns, building materials, construction techniques, and socio-economic make-up. The residences also represent the state's largest collection of nineteenth and early twentieth century frame houses. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining community.²

Summit County Recorder.

² From "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.

- 2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):
- 3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.


Photo No. 1: elevation. Camera facing .

Photo No. 2: elevation. Camera facing .

Photo No. 3: elevation. Camera facing .

Photo No. 4: elevation. Camera facing .

Kind of	Bldg. TES	St.	No. //6	Sant K	ege-
Class_3				4336	× 98.
Stories	Dimensions	Sq. Ft.	Factor	Totals	Total
1	x x	1016		8 4258	\$
	x x			,	
	x x				
Att. Gar.		Flr Walls	Cl		
	Description	of Buildings		Additions	Addition
Foundatio	on—Stone	Conc.	Sills		
	s alu Sed				
Roof Typ	Sable	Mtl. Pat			
	-Small Me		ge		
	nall Med _				
	-Front			162	
			5		
	e. Entry				
	mt. — ¼ ⅓ ½ ¾			2 80	
	r				
	-Apt Rms.	Fin. R	ms		
	ms Fin	Unfin			
	Class Basin Wtr. Sftr.	_ Tub	Trays	-	
	Basin	SinkT	oilet		
Plumbing	Wtr. Sftr.	Shr. St	O.T		1
	Dishwasher				
	ove H.A			- (1)	
	_ 🕝 Coal			300	
	. — Full				
Finish—F	ir. Hd. Wo	lPa	inel		
Floor-F	ir Hd. W	dOt	her		
Cabinets		ters.			+
Tile –Wa	llsWain	scot	Floors	120	
	sh-Wood D			120	
Awnings	— Metal	Fiberglas	s		
			-		
		V		1700	
Total Add		10.0		1300	+
Year Bui	lt. 1904 Avg.	1/9/9 Replac	ement Cost	3558	
1964		2. Obsole	scence	-	
Inf. by	Owner - Tenant Neighbor - Record		ld. Value		
	(reignbor - Record	- Est. Conv.	Factor	x.47	
		ement Cost—19	115		
	Depre	ciation Column	02345	6	
		ase Cost, Less I		1 MM	1
Total Val	ue from reverse sid	garag	e	17	
		Total Bu	ilding Val	ue \$	
	d ① 12- 2		8 By /	4.4	



RESIDENTIAL OUT BUILDINGS	Age	Size	Area	Fac- tor	Cost	Conv. Fac.	Adj. Cost	Depr. Value
		x				.47		
		x				.47		
		x				.47		
		x				.47		-
		x			11	.47		
	*	x				.47		1
Size 12 x 29 Age 3	5+	Cost	108		x 47 %	/		
Size x Age	× 25	_% Depr	108			6		77
1940 Base Cost	x 25	_% Depr	tion To	otal	tatio	n:		77
Average Yea	x 25 r of C	onstructure %	tion C	ompu	tatio	n:	45	77
1940 Base Cost	x 25 r of C	onstructure %	tion C	ompu	tatio	n:	45	77
Average Yea	x 25 r of C = .7.	_% Depr construction	etion C	otal compu / Y	tatio	n:	45	77
REMARKS 1901 S 4 1901	x 25 r of C = .7.	_% Depr construction	etion C	otal compu / Y	tatio	n:		77

	T+C-01	
	(M-70)	
	_	
	유	
8	a	
ST.	ĝ	֡
CATE OF	₢	֡
STATE OF	ŝ	֡
NAME OF TAXABLE PARTY.	βŔ	
NAME OF TAXABLE PARTY.	B E E	
No. of Contract of	S B A N	
COLUMN TO SERVICE STATE OF SERVICE STATE STATE OF SERVICE STATE STATE OF SERVICE STATE STA	S B A N	
STERNING TO STATE OF	BAN	
Deli Berranda del	BAN_	
CONTRACTOR OF THE PARTY OF THE	SAN	
CONTRACTOR OF	SAN L	֡
ALCOHOLD STREET, STREE	BAN L	֡
NAME AND ADDRESS OF THE OWNER, TH	SAN F	֡
CONTRACTOR DESCRIPTION OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN CO		֡
CONTRACTOR DESCRIPTION OF THE PARTY OF THE P	SAN	֡
SCOTTON STREET, ST.	SAN SA	֡
A CONTRACTOR DESCRIPTION OF	SAN AN	֡
A STATE OF THE PERSON NAMED IN		֡
The state of the s	SAN LAN	
Control of the last of the las		
The state of the s	DRBAN LAND	֡
	GAN LAND CARD	

Rory K & Linda Singer Box 1163 Park City, Utah 84060

PC 588 Blk 72 MR M97-821 M98-26-176

Beg 400 ft N & 344 ft W M/L of SW cor Sec16T2SR4E (being NW cor Lot 31 Blk 72 Park City Townsite, th S. 82° 15' W. 27.7 ft alg fence, th. S 5°27' E 51.0 ft & 2 ft outside existing

fence, th 9.80 ft S 68°58' E plus 2 ft outside existing fence, th S 2° 15.7 ft E. 40.60 ft, th N 84° 06.7 ft E 42.0 ft, 1 to 3 ft outside existing fence, th. N 2° 15.7 ft W 38.40 ft, th (Serial No.-Owner-Add.-Desc. of Property)

N 12°19' W 59.45 ft plus or - 2 ft outside existing fence, th S 82°15' W 15.80 ft alg wood fence to p.o.b. Also Lots 31 & N'ly 14ft Lot 32 Blk 72 Millsite Reservation to Park City										
									1 to	FRONTAGE OR AREA
										DEPTH FACTOR
									net	RATE
ASSESSED VALUE	-									CORNER INFLU- ENCE
ALUE	TOTAL									RATE
300	1500								2051	VALUE







